

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2016

Submitted Date:

12/21/2016

Document Number:

674703470**FIELD INSPECTION FORM**

Loc ID 335512	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED															
2A Doc Num: _____			Findings: 2 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested															
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																		
Contact Information:																		
<table border="1" style="width:100%"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Elsener, Garrett</td> <td></td> <td>garrett@caerusoilandgas.com</td> <td></td> </tr> <tr> <td>McKee, Michael</td> <td></td> <td>MMckee@caerusoilandgas.com</td> <td></td> </tr> <tr> <td>Janicek, Jake</td> <td></td> <td>JJanicek@caerusoilandgas.com</td> <td></td> </tr> </tbody> </table>				Contact Name	Phone	Email	Comment	Elsener, Garrett		garrett@caerusoilandgas.com		McKee, Michael		MMckee@caerusoilandgas.com		Janicek, Jake		JJanicek@caerusoilandgas.com
Contact Name	Phone	Email	Comment															
Elsener, Garrett		garrett@caerusoilandgas.com																
McKee, Michael		MMckee@caerusoilandgas.com																
Janicek, Jake		JJanicek@caerusoilandgas.com																

Contact Information:

Contact Name	Phone	Email	Comment
Elsener, Garrett		garrett@caerusoilandgas.com	
McKee, Michael		MMckee@caerusoilandgas.com	
Janicek, Jake		JJanicek@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293057	WELL	DG	09/05/2016	LO	045-14854	Puckett 31A-23	WO
293058	WELL	DG	09/10/2016	LO	045-14855	Puckett 31B-23	WO
293059	WELL	DG	09/18/2016	LO	045-14856	Puckett 31C-23	WO
293060	WELL	DG	09/24/2016	LO	045-14857	Puckett 31D-23	WO
293061	WELL	DG	10/25/2016	LO	045-14858	Puckett 33A-23	WO
293062	WELL	DG	10/06/2016	LO	045-14859	Puckett 32B-23	WO
293063	WELL	DG	10/12/2016	LO	045-14860	Puckett 32C-23	WO
293064	WELL	DG	10/18/2016	LO	045-14861	Puckett 32D-23	WO
447166	WELL	DG	11/21/2016		045-23279	Puckett 42B-23	WO
447167	WELL	DG	11/01/2016		045-23280	Puckett 42D-23	WO
447168	WELL	DG	11/14/2016		045-23281	Puckett 42A-23	WO
447169	WELL	DG	12/17/2016		045-23282	Puckett 41A-23	DG
447170	WELL	DG	11/07/2016		045-23283	Puckett 42C-23	WO
447171	WELL	DG	10/01/2016		045-23284	Puckett 32A-23	WO
447172	WELL	DG	12/05/2016		045-23285	Puckett 41C-23	WO
447173	WELL	DG	11/28/2016		045-23286	Puckett 41D-23	WO
447174	WELL	DG	12/11/2016		045-23287	Puckett 41B-23	WO

General Comment:

Location**Lease Road:**

Type	Main		
comment:	Snow packed		
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 335512 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective
Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>293057</u>	Type: <u>WELL</u>	API Number: <u>045-14854</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>293058</u>	Type: <u>WELL</u>	API Number: <u>045-14855</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>293059</u>	Type: <u>WELL</u>	API Number: <u>045-14856</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>293060</u>	Type: <u>WELL</u>	API Number: <u>045-14857</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>293061</u>	Type: <u>WELL</u>	API Number: <u>045-14858</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>293062</u>	Type: <u>WELL</u>	API Number: <u>045-14859</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>293063</u>	Type: <u>WELL</u>	API Number: <u>045-14860</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>293064</u>	Type: <u>WELL</u>	API Number: <u>045-14861</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>447166</u>	Type: <u>WELL</u>	API Number: <u>045-23279</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>447167</u>	Type: <u>WELL</u>	API Number: <u>045-23280</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>447168</u>	Type: <u>WELL</u>	API Number: <u>045-23281</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>447169</u>	Type: <u>WELL</u>	API Number: <u>045-23282</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

Well Drilling

Rig: Rig Name: H&P 330 Pusher/Rig Manager: George Urban
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: _____

Comment: Drilling surface hole.

Corrective Action: _____ Date: _____

Facility ID: <u>447170</u>	Type: <u>WELL</u>	API Number: <u>045-23283</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>447171</u>	Type: <u>WELL</u>	API Number: <u>045-23284</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>

Inspector Name: LONGWORTH, MIKE

Facility ID:	447172	Type:	WELL	API Number:	045-23285	Status:	DG	Insp. Status:	WO
Facility ID:	447173	Type:	WELL	API Number:	045-23286	Status:	DG	Insp. Status:	WO
Facility ID:	447174	Type:	WELL	API Number:	045-23287	Status:	DG	Insp. Status:	WO

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Vehicle Tracking	Pass	
				Covering Materials	Pass	
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703470	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4038331