

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/22/2016

Submitted Date:

12/22/2016

Document Number:

674703481**FIELD INSPECTION FORM**
 Loc ID 335230 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2716 | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 210824 | WELL | PR | 09/29/1989 | GW | 045-06582 | DOE 1-W-21 | PR |
| 272217 | WELL | PR | 10/06/2004 | GW | 045-10046 | FEDERAL PA 24-21 | PR |
| 272219 | WELL | PR | 10/12/2004 | GW | 045-10044 | FEDERAL PA 324-21 | PR |
| 272220 | WELL | PR | 10/13/2004 | GW | 045-10043 | FEDERAL PA 424-21 | PR |
| 272221 | WELL | PR | 10/15/2004 | GW | 045-10042 | FEDERAL PA 524-21 | PR |
| 278043 | WELL | PR | 12/01/2005 | GW | 045-10826 | FEDERAL PA 314-21 | PR |
| 278044 | WELL | PR | 01/06/2006 | GW | 045-10825 | FEDERAL PA 14-21 | PR |
| 278045 | WELL | PR | 11/24/2005 | GW | 045-10824 | FEDERAL PA 13-21 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 7 | | |

| | | | |
|-----------------------------------|---------------------|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Chemical containers | Date: | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 7 | | |
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 210824 | Type: | WELL | API Number: | 045-06582 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 272217 | Type: | WELL | API Number: | 045-10046 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 272219 | Type: | WELL | API Number: | 045-10044 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 272220 | Type: | WELL | API Number: | 045-10043 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 272221 | Type: | WELL | API Number: | 045-10042 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 278043 | Type: | WELL | API Number: | 045-10826 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 278044 | Type: | WELL | API Number: | 045-10825 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 278045 | Type: | WELL | API Number: | 045-10824 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Pass | |
| Ditches | Pass | | | | | |
| Berms | Pass | | | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 674703481 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4035985 |