

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2016

Submitted Date:

12/31/2016

Document Number:

666802852**FIELD INSPECTION FORM**

Loc ID 335294 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>
Axelsson, Aaron	970-230-0926	aaxelsson@vnrlc.com	<a href="#">Sr. Production Foreman</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211401	WELL	PR	08/15/1997	GW	045-07161	GIBSON GULCH UNIT 11-30	SI
268139	WELL	PR	08/11/2003	GW	045-09243	GIBSON GULCH UNIT 7-30 C	SI

**General Comment:**[Shared facilities with location ID 335467](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 2

Comment: Corrective Action: Date: 

Type: Emission Control Device

# 1

Comment: Corrective Action: Date: 

Type: Horizontal Heated Separator

# 8

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 2

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	500 BBLS	STEEL AST		39.496949,-107.597715

Comment: Corrective Action: Date: **Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: Corrective Action: Date:

<b>Venting:</b>			
Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 211401 Type: WELL API Number: 045-07161 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last producton posted number OCT 2016

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 268139 Type: WELL API Number: 045-09243 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last producton posted number OCT 2016

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
		Ditches	Pass			
Ditches	Pass					
Culverts	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT