

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/26/2016

Submitted Date:

01/03/2017

Document Number:

666802843

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
416774 \_\_\_\_\_ Murray, Richard \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416743	WELL	PR	01/03/2011	GW	045-19346	Burchfield RWF 44-32	PR
416751	WELL	PR	04/16/2011	GW	045-19349	Burchfield RWF 43-32	PR
416755	WELL	PR	05/31/2011	GW	045-19351	Burchfield RWF 544-32	PR
416757	WELL	PR	09/11/2014	GW	045-19352	Burchfield RWF 344-32	PR
416763	WELL	PR	09/11/2014	GW	045-19353	Burchfield RWF 534-32	PR
416764	WELL	PR	07/13/2011	GW	045-19354	Burchfield RWF 343-32	PR
416767	WELL	PR	05/31/2011	GW	045-19355	Burchfield RWF 443-32	PR
416775	WELL	PR	09/11/2014	GW	045-19357	Burchfield RWF 33-32	PR
416777	WELL	PR	05/03/2011	GW	045-19358	Burchfield RWF 533-32	PR
416778	WELL	PR	07/13/2011	GW	045-19359	Burchfield RWF 333-32	PR
416786	WELL	PR	10/06/2014	GW	045-19362	Burchfield RWF 34-32	PR
416788	WELL	PR	05/31/2011	GW	045-19363	Burchfield RWF 543-32	PR
416795	WELL	PR	04/16/2011	GW	045-19365	Burchfield RWF 434-32	PR
416797	WELL	PR	07/13/2011	OW	045-19366	Burchfield RWF 433-32	PR
416803	WELL	PR	02/28/2011	GW	045-19367	Burchfield RWF 444-32	PR
416807	WELL	PR	02/28/2011	GW	045-19370	Burchfield RWF 334-32	PR

**General Comment:**



Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.477655,-107.905208	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	416743	Type:	WELL	API Number:	045-19346	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				
Facility ID:	416751	Type:	WELL	API Number:	045-19349	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				
Facility ID:	416755	Type:	WELL	API Number:	045-19351	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				
Facility ID:	416757	Type:	WELL	API Number:	045-19352	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				
Facility ID:	416763	Type:	WELL	API Number:	045-19353	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				
Facility ID:	416764	Type:	WELL	API Number:	045-19354	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				
Facility ID:	416767	Type:	WELL	API Number:	045-19355	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				
Facility ID:	416775	Type:	WELL	API Number:	045-19357	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:					Date:				

Facility ID: 416777	Type: WELL	API Number: 045-19358	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	
Facility ID: 416778	Type: WELL	API Number: 045-19359	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	
Facility ID: 416786	Type: WELL	API Number: 045-19362	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	
Facility ID: 416788	Type: WELL	API Number: 045-19363	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	
Facility ID: 416795	Type: WELL	API Number: 045-19365	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	
Facility ID: 416797	Type: WELL	API Number: 045-19366	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	
Facility ID: 416803	Type: WELL	API Number: 045-19367	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	
Facility ID: 416807	Type: WELL	API Number: 045-19370	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger Lift				
Corrective Action:			Date:	



**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: OFF Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Ditches	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT