

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/30/2016

Submitted Date:

01/04/2017

Document Number:

666802854**FIELD INSPECTION FORM**

Loc ID 335239 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300230	WELL	PR	05/21/2012	GW	045-17866	JOLLEY KP 332-17	PR
300231	WELL	PR	08/26/2016	GW	045-17865	JOLLEY KP 32-17	PR
300232	WELL	PR	04/01/2012	GW	045-17864	JOLLEY KP 432-17	PR
300334	WELL	PR	04/01/2012	GW	045-17893	JOLLEY KP 531-17	PR
300335	WELL	PR	04/01/2012	GW	045-17894	JOLLEY KP 542-17	PR
300336	WELL	PR	08/05/2016	GW	045-17895	JOLLEY KP 442-17	PR
300337	WELL	PR	04/01/2012	GW	045-17896	JOLLEY KP 342-17	PR
300338	WELL	PR	04/01/2012	GW	045-17897	JOLLEY KP 42-17	PR
300339	WELL	PR	05/21/2012	GW	045-17898	JOLLEY KP 541-17	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-2168-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 9		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical units, 2 at wellhead, 1 at Gas meter run		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		39.530251,-107.575513
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	2	300 BBLs	STEEL AST		39.530224,-107.575494	
Comment: Fresh water for fire suppression						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content) Fresh water						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLs	STEEL AST		,	
Comment: Centralized battery						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	YES					
Comment:	Bradenhead valves open					
Corrective Action:						Date:
<u>Flaring:</u>						

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	300230	Type:	WELL	API Number:	045-17866	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300231	Type:	WELL	API Number:	045-17865	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300232	Type:	WELL	API Number:	045-17864	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300334	Type:	WELL	API Number:	045-17893	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300335	Type:	WELL	API Number:	045-17894	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300336	Type:	WELL	API Number:	045-17895	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300337	Type:	WELL	API Number:	045-17896	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300338	Type:	WELL	API Number:	045-17897	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	300339	Type:	WELL	API Number:	045-17898	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: [Plunger lift](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
Berms	Pass					
Seeding	Pass					
		Ditches	Pass			
Drains	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT