

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2017

Submitted Date:

01/04/2017

Document Number:

666802857**FIELD INSPECTION FORM**
 Loc ID 334742 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256759	WELL	PR	12/12/2003	GW	045-07497	MILLER 14-2	PR
273453	WELL	PR	11/11/2010	GW	045-10248	CEDAR SPRINGS RANCH 11-14D (B14W)	PR
273454	WELL	PR	02/03/2005	OW	045-10247	CEDAR SPRINGS RANCH 11-15D (B14W)	TA

General Comment:

Action required items noted on previous inspection have been satisfied

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

3

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

2

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	OTHER			39.449739,-107.741624	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)	250bbbs					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 256759 Type: WELL API Number: 045-07497 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 273453 Type: WELL API Number: 045-10248 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 273454 Type: WELL API Number: 045-10247 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Current Form 4 on file to maintain Temporarily Abandoned well status

Corrective Action:

Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Seeding	Pass					
		Culverts	Pass			
Ditches	Pass					
		Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT