

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2017

Submitted Date:

01/04/2017

Document Number:

674004735**FIELD INSPECTION FORM**

Loc ID 328106 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247757	WELL	PR	09/15/1993	GW	123-15555	HICKS & JOHNSON DRAKE FM 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		40.236140,-104.925630	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	75 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:		Shared with crude oil tank.			
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 247757 Type: WELL API Number: 123-15555 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Shut in at separator

Corrective Action: _____ Date: _____

BradenHeadComment: Bradenhead plumbed to surface.

Corrective Action: _____ Date: _____

Environmental		
Spill/Remediation:		
Comment:		
Corrective Action:		Date: _____
Emission Control Burner (ECB): YES _____		
Comment:	Well shut in	
Pilot: OFF _____	Wildlife Protection Devices (fired vessels): YES _____	
COGCC Comments		
Comment	User	Date
Routine inspection.	carlilec	01/04/2017