

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2017

Submitted Date:

01/04/2017

Document Number:

675103236**FIELD INSPECTION FORM**

Loc ID 315799 Inspector Name: GRANAHAN, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10066Name of Operator: MATRIX PRODUCTION COMPANYAddress: 5725 COMMONWEALTH BLVDCity: SUGAR LAND State: TX Zip: 77479**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
thompson, pat	(281) 265-1212	pthompson@matrix-companies.com	booco

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231587	WELL	PR	06/26/1989	OW	103-09258	TEXACO-SULLIVAN,MC (NCT-1) 1	PR

General Comment:

Blowing snow/snow drifts prevented access to location at top of hill. Evidence of roads plowed and maintained routinely - just not at time of inspection. Unable to determine if corrective actions from previous inspection doc # 673402538 have been implemented.

