

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/04/2017
Submitted Date:
01/04/2017
Document Number:
675103237

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GRANAHAN, KYLE On-Site Inspection
315795 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10066
Name of Operator: MATRIX PRODUCTION COMPANY
Address: 5725 COMMONWEALTH BLVD
City: SUGAR LAND State: TX Zip: 77479

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
thompson, pat	(281) 265-1212	pthompson@matrix-companies.com	booco

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231579	WELL	PR	12/29/1985	OW	103-09250	SEELY LAND & LIVESTOCK 1	PR

General Comment:

Blowing snow/snow drifts prevented access to location at top of hill. Evidence of roads plowed and maintained routinely - just not at time of inspection. Unable to determine if corrective actions from previous inspection doc # 673402539 have been implemented.

Inspected Facilities

Facility ID: 231579 Type: WELL API Number: 103-09250 Status: PR Insp. Status: PR