

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2017

Submitted Date:

01/06/2017

Document Number:

666802859**FIELD INSPECTION FORM**
 Loc ID 334643 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270931	WELL	PR	06/11/2004	GW	045-09805	SOURS 15-11A (L15W)	PR
270932	WELL	PR	05/07/2013	GW	045-09804	SOURS 15-11B (L15W)	PR
270940	WELL	PR	11/05/2012	GW	045-09803	SOURS 15-13A (L15W)	PR
271504	WELL	PR	06/02/2004	GW	045-09896	SOURS 15-14A (L15W)	PR
275900	WELL	PR	11/01/2012	GW	045-10396	ROSE 15-12A (L15W)	PR
275901	WELL	PR	08/23/2005	GW	045-10397	ROSE 15-11D (L15W)	PR
275902	WELL	PR	09/01/2011	GW	045-10398	ROSE 15-13D (L15W)	PR
275903	WELL	PR	08/30/2005	GW	045-10399	ROSE 15-15B (L15W)	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0840-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Heated Separator	# 8		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		39.443768,-107.768067	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	270931	Type:	WELL	API Number:	045-09805	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	270932	Type:	WELL	API Number:	045-09804	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	270940	Type:	WELL	API Number:	045-09803	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	271504	Type:	WELL	API Number:	045-09896	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	275900	Type:	WELL	API Number:	045-10396	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	275901	Type:	WELL	API Number:	045-10397	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	275902	Type:	WELL	API Number:	045-10398	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	275903	Type:	WELL	API Number:	045-10399	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT