

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2017

Submitted Date:

01/06/2017

Document Number:

666802864

FIELD INSPECTION FORM

Loc ID 334675 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

- 11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265798	WELL	PR	07/29/2003	GW	045-09056	ROSE RANCH 11-12B (I10B)	PR
265799	WELL	PR	07/25/2003	GW	045-09057	ROSE RANCH 10-16C (I10B)	SI
265802	WELL	PR	06/11/2004	GW	045-09060	ROSE RANCH 11-12C (I10B)	PR
265803	WELL	PR	07/26/2003	GW	045-09061	ROSE RANCH 10-10C (I10B)	PR
265814	WELL	PR	07/25/2003	GW	045-09065	ROSE RANCH 10-8C (I10B)	PR
269805	WELL	PR	03/20/2004	GW	045-09412	ROSE RANCH 10-10A (I10B)	PR
269806	WELL	PR	03/20/2004	GW	045-09410	ROSE RANCH 10-9D(I10B)	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	AIRS ID 045-0651		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	<input style="width: 80%; border: 1px solid black;" type="text"/>
Other (Content)	<input style="width: 95%; border: 1px solid black;" type="text"/>
Other (Capacity)	<input style="width: 95%; border: 1px solid black;" type="text"/>
Other (Type)	<input style="width: 95%; border: 1px solid black;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		39.456908,-107.756783
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:


Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities										
Facility ID:	265798	Type:	WELL	API Number:	045-09056	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	265799	Type:	WELL	API Number:	045-09057	Status:	PR	Insp. Status:	SI	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Idle Well										
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: _____					
Comment:	Last posted production number OCT 2016									
Corrective Action:							Date:			
Facility ID:	265802	Type:	WELL	API Number:	045-09060	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	265803	Type:	WELL	API Number:	045-09061	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	265814	Type:	WELL	API Number:	045-09065	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	269805	Type:	WELL	API Number:	045-09412	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	269806	Type:	WELL	API Number:	045-09410	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			



Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT