

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/06/2017
Submitted Date:
01/06/2017
Document Number:
685501684

FIELD INSPECTION FORM

Loc ID 431617 Inspector Name: MONTOYA, JOHN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections
REDDY, LUKE		Luke.Reddy@anadarko.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431614	WELL	AL	12/17/2014	LO	123-36690	TURKEY SPRINGS 29N-14HZ	AL
431615	WELL	PR	10/26/2013	OW	123-36691	TURKEY SPRINGS 3N-14HZ	PR
431616	WELL	PR	10/31/2013	OW	123-36692	TURKEY SPRINGS 3C-14HZ	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	OK		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	ROD IRON FENCES ON 2 WELLHEADS SE CORNER N40.07732 W-104.44558		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 431614 Type: WELL API Number: 123-36690 Status: AL Insp. Status: AL

Facility ID: 431615 Type: WELL API Number: 123-36691 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE

Corrective Action:

Date:

Facility ID: 431616 Type: WELL API Number: 123-36692 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING Pass

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION Pass

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS Pass

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEADS	montoyaj	01/06/2017