

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2017

Submitted Date:

01/06/2017

Document Number:

666802870**FIELD INSPECTION FORM**
 Loc ID 334610 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email                        | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General |       | cogcc.inspections@encana.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 270995      | WELL | PR     | 01/07/2004  | GW         | 045-09809 | BASS 14-10A (G14W) | PR          |
| 271010      | WELL | PR     | 12/08/2004  | GW         | 045-09822 | BASS 14-6D (G14W)  | PR          |
| 271011      | WELL | PR     | 12/11/2004  | GW         | 045-09823 | BASS 14-14A (G14W) | PR          |
| 271012      | WELL | PR     | 12/24/2004  | GW         | 045-09824 | BASS 14-7B (G14W)  | PR          |
| 271013      | WELL | PR     | 12/20/2004  | GW         | 045-09825 | BASS 14-2D(G14W)   | PR          |
| 271014      | WELL | PR     | 12/15/2004  | GW         | 045-09826 | BASS 14-11B(G14W)  | PR          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

# 5

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 1

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 6

Comment: Corrective Action: Date: 

Type: Horizontal Heated Separator

# 1

Comment: Corrective Action: Date: **Tanks and Berms:**

| Contents | # | Capacity | Type      | Tank ID | SE GPS |
|----------|---|----------|-----------|---------|--------|
| METHANOL | 1 | 1000 GAL | STEEL AST |         | ,      |

Comment: Centralized battery

Corrective Action: Date: **Paint**

Condition Adequate

Other (Content) Other (Capacity) Other (Type) **Berms**

| Type               | Capacity             | Permeability (Wall) | Permeability (Base) | Maintenance                |
|--------------------|----------------------|---------------------|---------------------|----------------------------|
|                    |                      |                     |                     |                            |
| Comment:           | <input type="text"/> |                     |                     | <input type="text"/>       |
| Corrective Action: | <input type="text"/> |                     |                     | Date: <input type="text"/> |

|                    |          |                     |                     |             |                       |       |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|-------|
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| CONDENSATE         | 2        | 500 BBLs            | STEEL AST           |             | 39.444062,-107.741326 |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Paint</b>       |          |                     |                     |             |                       |       |
| Condition          | Adequate |                     |                     |             |                       |       |
| Other (Content)    |          |                     |                     |             |                       |       |
| Other (Capacity)   |          |                     |                     |             |                       |       |
| Other (Type)       |          |                     |                     |             |                       |       |
| <b>Berms</b>       |          |                     |                     |             |                       |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Venting:</b>    |          |                     |                     |             |                       |       |
| Yes/No             |          |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Flaring:</b>    |          |                     |                     |             |                       |       |
| Type               |          |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |

| Inspected Facilities  |              |       |      |             |           |         |    |               |    |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 270995       | Type: | WELL | API Number: | 045-09809 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 271010       | Type: | WELL | API Number: | 045-09822 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 271011       | Type: | WELL | API Number: | 045-09823 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 271012       | Type: | WELL | API Number: | 045-09824 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 271013       | Type: | WELL | API Number: | 045-09825 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 271014       | Type: | WELL | API Number: | 045-09826 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |

| Environmental                     |  |
|-----------------------------------|--|
| <b>Spill/Remediation:</b>         |  |
| Comment:                          |  |
| Corrective Action:                | <div></div> <div>Date: </div>                    |
| Emission Control Burner (ECB): NO |  |
| Comment:                          |  |
| Pilot:                            | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: 

Smow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT