

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/26/2016

Submitted Date:

01/03/2017

Document Number:

666802841

### FIELD INSPECTION FORM

Loc ID 334779	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> <u>24</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

<b>Contact Information:</b>			
Contact Name , Inspections	Phone	Email COGCCInspectionReports@terraep.com	Comment <a href="#">Field Inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289341	WELL	PR		GW	045-13737	HARRIS RWF 431-5	PR
289342	WELL	PR	08/31/2008	GW	045-13736	HARRIS RWF 533-5	PR
289343	WELL	PR		GW	045-13735	HARRIS RWF 333-5	PR
289344	WELL	PR		GW	045-13734	HARRIS RWF 33-5	PR
289345	WELL	PR	10/31/2008	GW	045-13733	HARRIS RWF 433-5	PR
289346	WELL	PR		GW	045-13732	HARRIS RWF 331-5	PR
289347	WELL	PR		GW	045-13731	HARRIS RWF 31-5	PR
289348	WELL	PR		GW	045-13730	HARRIS RWF 332-5	PR
289349	WELL	PR		GW	045-13729	HARRIS RWF 531-5	PR
289350	WELL	PR		GW	045-13728	HARRIS RWF 32-5	PR
289351	WELL	PR		GW	045-13727	HARRIS RWF 432-5	PR
289352	WELL	PR		GW	045-13726	HARRIS RWF 532-5	PR
289353	WELL	PR		GW	045-13725	HARRIS RWF 541-5	PR
289354	WELL	PR		GW	045-13724	HARRIS RWF 341-5	PR
289355	WELL	PR		GW	045-13723	HARRIS RWF 441-5	PR
289356	WELL	PR		GW	045-13722	HARRIS RWF 342-5	PR
289360	WELL	PR		GW	045-13718	HARRIS RWF 43-5	PR

<b>General Comment:</b>
-------------------------

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1912-001		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Landowners equipment on location		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Emission Control Device	# 1				
Plunger Lift	# 17				
Horizontal Heated Separator	# 17				
Ancillary equipment	# 3	Chemical units at wellhead			

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:	Centralized battery				
Corrective Action:				Date:	

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		39.467807,-107.910244
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES
Comment:	Bradenhead valves open
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	289341	Type:	WELL	API Number:	045-13737	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	289342	Type:	WELL	API Number:	045-13736	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	289343	Type:	WELL	API Number:	045-13735	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	289344	Type:	WELL	API Number:	045-13734	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	289345	Type:	WELL	API Number:	045-13733	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	289346	Type:	WELL	API Number:	045-13732	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	289347	Type:	WELL	API Number:	045-13731	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	289348	Type:	WELL	API Number:	045-13730	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 289349	Type: WELL	API Number: 045-13729	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		
Facility ID: 289350	Type: WELL	API Number: 045-13728	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		
Facility ID: 289351	Type: WELL	API Number: 045-13727	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		
Facility ID: 289352	Type: WELL	API Number: 045-13726	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		
Facility ID: 289353	Type: WELL	API Number: 045-13725	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		
Facility ID: 289354	Type: WELL	API Number: 045-13724	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		
Facility ID: 289355	Type: WELL	API Number: 045-13723	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		
Facility ID: 289356	Type: WELL	API Number: 045-13722	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:		Date:		

Facility ID: 289360 Type: WELL API Number: 045-13718 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

[Disconnected](#)

Pilot: OFF

Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					
Seeding	Pass					

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802841	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4044176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4044176</a>