

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/26/2016

Submitted Date:

01/03/2017

Document Number:

666802843**FIELD INSPECTION FORM**

Loc ID 416774	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>20</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416743	WELL	PR	01/03/2011	GW	045-19346	Burchfield RWF 44-32	PR
416751	WELL	PR	04/16/2011	GW	045-19349	Burchfield RWF 43-32	PR
416755	WELL	PR	05/31/2011	GW	045-19351	Burchfield RWF 544-32	PR
416757	WELL	PR	09/11/2014	GW	045-19352	Burchfield RWF 344-32	PR
416763	WELL	PR	09/11/2014	GW	045-19353	Burchfield RWF 534-32	PR
416764	WELL	PR	07/13/2011	GW	045-19354	Burchfield RWF 343-32	PR
416767	WELL	PR	05/31/2011	GW	045-19355	Burchfield RWF 443-32	PR
416775	WELL	PR	09/11/2014	GW	045-19357	Burchfield RWF 33-32	PR
416777	WELL	PR	05/03/2011	GW	045-19358	Burchfield RWF 533-32	PR
416778	WELL	PR	07/13/2011	GW	045-19359	Burchfield RWF 333-32	PR
416786	WELL	PR	10/06/2014	GW	045-19362	Burchfield RWF 34-32	PR
416788	WELL	PR	05/31/2011	GW	045-19363	Burchfield RWF 543-32	PR
416795	WELL	PR	04/16/2011	GW	045-19365	Burchfield RWF 434-32	PR
416797	WELL	PR	07/13/2011	OW	045-19366	Burchfield RWF 433-32	PR
416803	WELL	PR	02/28/2011	GW	045-19367	Burchfield RWF 444-32	PR
416807	WELL	PR	02/28/2011	GW	045-19370	Burchfield RWF 334-32	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical units at wellhead		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.477655,-107.905208	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	416743	Type:	WELL	API Number:	045-19346	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416751	Type:	WELL	API Number:	045-19349	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416755	Type:	WELL	API Number:	045-19351	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416757	Type:	WELL	API Number:	045-19352	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416763	Type:	WELL	API Number:	045-19353	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416764	Type:	WELL	API Number:	045-19354	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416767	Type:	WELL	API Number:	045-19355	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416775	Type:	WELL	API Number:	045-19357	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			

Facility ID:	416777	Type:	WELL	API Number:	045-19358	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416778	Type:	WELL	API Number:	045-19359	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416786	Type:	WELL	API Number:	045-19362	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416788	Type:	WELL	API Number:	045-19363	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416795	Type:	WELL	API Number:	045-19365	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416797	Type:	WELL	API Number:	045-19366	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416803	Type:	WELL	API Number:	045-19367	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	416807	Type:	WELL	API Number:	045-19370	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger Lift								
Corrective Action:						Date:			

--

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: [Disconnected](#)

Pilot: OFF

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Ditches	Pass			
Seeding	Pass					

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802843	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4044178