

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/10/2017

Submitted Date:

01/11/2017

Document Number:

666802878**FIELD INSPECTION FORM**

|  |                                    |   |                   |   |
|--|------------------------------------|---|-------------------|---|
| Loc ID<br>432398   | Inspector Name:<br>Murray, Richard | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| <b>Operator Information:</b><br>OGCC Operator Number: <u>96850</u><br>Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u><br>Address: <u>PO BOX 370</u><br>City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u> |                                    |   |                   | <b>Findings:</b><br>19 Number of Comments<br>0 Number of Corrective Actions<br><input type="checkbox"/> Corrective Action Response Requested  |

**Contact Information:**

| Contact Name  | Phone | Email                              | Comment           |
|---------------|-------|------------------------------------|-------------------|
| , Inspections |       | COGCCInspectionReports@terraep.com | Field Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 432396      | WELL | PR     | 04/30/2014  | GW         | 045-21978 | Savage RWF 314-25 | PR          |
| 432397      | WELL | PR     | 03/07/2014  | OW         | 045-21979 | Savage RWF 24-25  | PR          |
| 432399      | WELL | PR     | 03/07/2014  | OW         | 045-21980 | Savage RWF 14-25  | PR          |
| 432400      | WELL | PR     | 04/30/2014  | GW         | 045-21981 | Savage RWF 413-25 | PR          |
| 432401      | WELL | PR     | 03/07/2014  | OW         | 045-21982 | Savage RWF 424-25 | PR          |
| 432402      | WELL | PR     | 06/02/2014  | GW         | 045-21983 | Savage RWF 13-25  | PR          |
| 432403      | WELL | PR     | 04/30/2014  | GW         | 045-21984 | Savage RWF 414-25 | PR          |
| 432404      | WELL | PR     | 06/30/2014  | GW         | 045-21985 | Savage RWF 23-25  | PR          |
| 432405      | WELL | PR     | 06/30/2014  | GW         | 045-21986 | Savage RWF 423-25 | PR          |
| 432406      | WELL | PR     | 06/30/2014  | GW         | 045-21987 | Savage RWF 313-25 | PR          |
| 432407      | WELL | PR     | 03/07/2014  | OW         | 045-21988 | Savage RWF 324-25 | PR          |
| 432408      | WELL | PR     | 04/30/2014  | GW         | 045-21989 | Savage RWF 514-25 | PR          |
| 432409      | WELL | PR     | 06/30/2014  | GW         | 045-21990 | Savage RWF 323-25 | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | BATTERY              |       |  |
| Comment:           | AIRS ID 045-2354-002 |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| Type                              | #    | Comment                    | Corrective Action | Date  | corrective date |
|-----------------------------------|------|----------------------------|-------------------|-------|-----------------|
| Type: Emission Control Device     | # 1  |                            |                   |       |                 |
| Comment:                          |      |                            |                   |       |                 |
| Corrective Action:                |      |                            |                   | Date: |                 |
| Type: Plunger Lift                | # 13 |                            |                   |       |                 |
| Comment:                          |      |                            |                   |       |                 |
| Corrective Action:                |      |                            |                   | Date: |                 |
| Type: Horizontal Heated Separator | # 13 |                            |                   |       |                 |
| Comment:                          |      |                            |                   |       |                 |
| Corrective Action:                |      |                            |                   | Date: |                 |
| Type: Gas Meter Run               | # 1  |                            |                   |       |                 |
| Comment:                          |      |                            |                   |       |                 |
| Corrective Action:                |      |                            |                   | Date: |                 |
| Type: Ancillary equipment         | # 2  |                            |                   |       |                 |
| Comment:                          |      | Chemical units at wellhead |                   |       |                 |
| Corrective Action:                |      |                            |                   | Date: |                 |
| Type: Vertical Separator          | # 2  |                            |                   |       |                 |
| Comment:                          |      |                            |                   |       |                 |
| Corrective Action:                |      |                            |                   | Date: |                 |

**Tanks and Berms:**

| Contents           | #                   | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---------------------|----------|-----------|---------|--------|
| PRODUCED WATER     | 2                   | 300 BBLS | STEEL AST |         | ,      |
| Comment:           | Centralized battery |          |           |         |        |
| Corrective Action: |                     |          |           | Date:   |        |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|                    |          |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

|                    |   |          |           |         |                       |       |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |       |
| CONDENSATE         | 2 | 300 BBLs | STEEL AST |         | 39.493747,-107.837694 |       |
| Comment:           |   |          |           |         |                       |       |
| Corrective Action: |   |          |           |         |                       | Date: |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

Venting:

|                    |                        |       |  |
|--------------------|------------------------|-------|--|
| Yes/No             | YES                    |       |  |
| Comment:           | Bradenhead valves open |       |  |
| Corrective Action: |                        | Date: |  |

Flaring:

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |              |       |      |             |           |         |    |               |    |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 432396       | Type: | WELL | API Number: | 045-21978 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432397       | Type: | WELL | API Number: | 045-21979 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432399       | Type: | WELL | API Number: | 045-21980 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432400       | Type: | WELL | API Number: | 045-21981 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432401       | Type: | WELL | API Number: | 045-21982 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432402       | Type: | WELL | API Number: | 045-21983 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432403       | Type: | WELL | API Number: | 045-21984 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432404       | Type: | WELL | API Number: | 045-21985 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432405 | Type: | WELL | API Number: | 045-21986 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432406 | Type: | WELL | API Number: | 045-21987 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432407 | Type: | WELL | API Number: | 045-21988 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432408 | Type: | WELL | API Number: | 045-21989 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432409 | Type: | WELL | API Number: | 045-21990 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

| Environmental                      |  |
|------------------------------------|--|
| <b>Spill/Remediation:</b>          |  |
| Comment:                           |  |
| Corrective Action:                 | Date:  |
| Emission Control Burner (ECB): YES |  |
| Comment:                           |  |
| Pilot: ON                          | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT