

Reclamation Inspection

01/09/2017

Operator: Atlas Resources

Location ID: 314073

Phillips County, CO

SWNW Section 36 T9N R44W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo of sign at well.



Figure 2: Photo taken from the north east end of the location, facing south. Photo shows vegetation over the reclamation area.



Figure 3: Photo taken from the north east end of the location, facing west. Photo shows vegetation over the reclamation area.



Figure 4: Photo taken from the northwest corner of the location, facing south. Photo shows vegetation over the reclamation area.



Figure 5: Photo taken from the northwest corner of the location, facing east. Photo shows vegetation over the reclamation area.



Figure 6: Photo taken from the southwest corner of the location, facing north. Photo shows vegetation over the reclamation area.



Figure 7: Photo taken from the southwest corner of the location, facing east. Photo shows vegetation over the reclamation area.



Figure 8: Photo taken from the southeast corner of the location, facing west. Photo shows vegetation over the reclamation area.



Figure 9: Photo taken from the southeast corner of the location, facing north. Photo shows vegetation over the reclamation area.