

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/11/2017

Submitted Date:

01/12/2017

Document Number:

666802882**FIELD INSPECTION FORM**

Loc ID 334693	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL &amp; GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				<b>Findings:</b> <u>13</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285600	WELL	PR	06/14/2010	GW	045-12525	COUEY 24-6 (F24W)	PR
285601	WELL	PR	07/12/2007	GW	045-12524	COUEY FEDERAL 24-3 (F24W)	PR
285602	WELL	PR	07/15/2007	GW	045-12523	COUEY FEDERAL 24-3D (F24W)	PR
293065	WELL	PR	02/01/2011	GW	045-14862	COUEY 24-7 (F24W)	PR
293066	WELL	PR	01/01/2011	GW	045-14863	COUEY 24-10B (F24W)	PR
293067	WELL	PR	09/21/2008	GW	045-14864	COUEY 24-10 (F24W)	PR
293068	WELL	PR	02/01/2011	GW	045-14865	COUEY 24-11 (F24W)	PR
293159	WELL	PR	02/01/2011	GW	045-14907	COUEY 24-2D (F24W)	PR
293394	WELL	PR	05/01/2014	GW	045-14954	COUEY 24-6D (F24W)	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1542-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		39.434588,-107.727385	
Comment:						
Corrective Action:				Date:		
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	285600	Type:	WELL	API Number:	045-12525	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285601	Type:	WELL	API Number:	045-12524	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285602	Type:	WELL	API Number:	045-12523	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	293065	Type:	WELL	API Number:	045-14862	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	293066	Type:	WELL	API Number:	045-14863	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	293067	Type:	WELL	API Number:	045-14864	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	293068	Type:	WELL	API Number:	045-14865	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	293159	Type:	WELL	API Number:	045-14907	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	293394	Type:	WELL	API Number:	045-14954	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Plunger lift		
Corrective Action:		Date:	

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Ditches	Pass					
		Culverts	Pass			
Seeding	Pass					

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT