

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2017

Submitted Date:

01/06/2017

Document Number:

666802864**FIELD INSPECTION FORM**

Loc ID 334675	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 11 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																															
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>																																																																			
Contact Information: <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Contact, General</td> <td></td> <td>cogcc.inspections@encana.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	Contact, General		cogcc.inspections@encana.com																																																								
Contact Name	Phone	Email	Comment																																																																
Contact, General		cogcc.inspections@encana.com																																																																	
Inspected Facilities: <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>265798</td> <td>WELL</td> <td>PR</td> <td>07/29/2003</td> <td>GW</td> <td>045-09056</td> <td>ROSE RANCH 11-12B (I10B)</td> <td>PR</td> </tr> <tr> <td>265799</td> <td>WELL</td> <td>PR</td> <td>07/25/2003</td> <td>GW</td> <td>045-09057</td> <td>ROSE RANCH 10-16C (I10B)</td> <td>SI</td> </tr> <tr> <td>265802</td> <td>WELL</td> <td>PR</td> <td>06/11/2004</td> <td>GW</td> <td>045-09060</td> <td>ROSE RANCH 11-12C (I10B)</td> <td>PR</td> </tr> <tr> <td>265803</td> <td>WELL</td> <td>PR</td> <td>07/26/2003</td> <td>GW</td> <td>045-09061</td> <td>ROSE RANCH 10-10C (I10B)</td> <td>PR</td> </tr> <tr> <td>265814</td> <td>WELL</td> <td>PR</td> <td>07/25/2003</td> <td>GW</td> <td>045-09065</td> <td>ROSE RANCH 10-8C (I10B)</td> <td>PR</td> </tr> <tr> <td>269805</td> <td>WELL</td> <td>PR</td> <td>03/20/2004</td> <td>GW</td> <td>045-09412</td> <td>ROSE RANCH 10-10A (I10B)</td> <td>PR</td> </tr> <tr> <td>269806</td> <td>WELL</td> <td>PR</td> <td>03/20/2004</td> <td>GW</td> <td>045-09410</td> <td>ROSE RANCH 10-9D(I10B)</td> <td>PR</td> </tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	265798	WELL	PR	07/29/2003	GW	045-09056	ROSE RANCH 11-12B (I10B)	PR	265799	WELL	PR	07/25/2003	GW	045-09057	ROSE RANCH 10-16C (I10B)	SI	265802	WELL	PR	06/11/2004	GW	045-09060	ROSE RANCH 11-12C (I10B)	PR	265803	WELL	PR	07/26/2003	GW	045-09061	ROSE RANCH 10-10C (I10B)	PR	265814	WELL	PR	07/25/2003	GW	045-09065	ROSE RANCH 10-8C (I10B)	PR	269805	WELL	PR	03/20/2004	GW	045-09412	ROSE RANCH 10-10A (I10B)	PR	269806	WELL	PR	03/20/2004	GW	045-09410	ROSE RANCH 10-9D(I10B)	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																												
265798	WELL	PR	07/29/2003	GW	045-09056	ROSE RANCH 11-12B (I10B)	PR																																																												
265799	WELL	PR	07/25/2003	GW	045-09057	ROSE RANCH 10-16C (I10B)	SI																																																												
265802	WELL	PR	06/11/2004	GW	045-09060	ROSE RANCH 11-12C (I10B)	PR																																																												
265803	WELL	PR	07/26/2003	GW	045-09061	ROSE RANCH 10-10C (I10B)	PR																																																												
265814	WELL	PR	07/25/2003	GW	045-09065	ROSE RANCH 10-8C (I10B)	PR																																																												
269805	WELL	PR	03/20/2004	GW	045-09412	ROSE RANCH 10-10A (I10B)	PR																																																												
269806	WELL	PR	03/20/2004	GW	045-09410	ROSE RANCH 10-9D(I10B)	PR																																																												
General Comment: <div style="height: 150px; border: 1px solid black;"></div>																																																																			

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0651		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Heated Separator	# 7		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		39.456908,-107.756783
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	265798	Type:	WELL	API Number:	045-09056	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	265799	Type:	WELL	API Number:	045-09057	Status:	PR	Insp. Status:	SI
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____								
Comment:	Last posted production number OCT 2016								
Corrective Action:						Date:			
Facility ID:	265802	Type:	WELL	API Number:	045-09060	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	265803	Type:	WELL	API Number:	045-09061	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	265814	Type:	WELL	API Number:	045-09065	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	269805	Type:	WELL	API Number:	045-09412	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	269806	Type:	WELL	API Number:	045-09410	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			



Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401179572	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046160