



photo 1: Facing northwest toward the location which has a perimeter fence.



photo 2: Center of the location facing north.



photo 3: Center of the location facing west.



photo 4: Center of the location facing south.



photo 5: Center of the location facing east.



photo 6: Area at center of the location (approx. 100x50') with little to no vegetation growth.



photo 7: Undesirable weed growth (Kochia). The 3 ft. shovel indicates height of weed growth.



photo 8: North side of the location facing south.



photo 9: View of groundcover. There is predominantly undesirable weed growth (Kochia) throughout the location.



photo 10: Facing east toward the surrounding undisturbed pasture.