



**photo 1:** Facing north toward the location.



**photo 2:** A sign is located at the entrance of the location.





**photo 3:** The soils have been ripped around the location for surface roughening BMP.



**photo 4:** Facing northwest toward the location.





**photo 5:** Facing north at the east side of the location.



**photo 6:** Tanks are stored at the northeast side of the location. A berm is placed around the tanks.





**photo 7:** There is a dirt pile at the northwest side of the location.



**photo 8:** Facing south along the west side of the location.



**photo 9:** Southwest side of the location facing northeast.