



photo 1: Facing east at the beginning of the access road toward the location.



photo 2: Facing east along the access road.



photo 3: Facing east toward the location.



photo 4: Wellhead and sign at center of the location.



photo 5: North side of the location facing south.



photo 6: Facing southeast toward the location.



photo 7: A cover crop (Oats) stubble appears to be the dominant cover which will not grow back during the next growing season.