

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2017

Submitted Date:

01/13/2017

Document Number:

666802892**FIELD INSPECTION FORM**

Loc ID 432336	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 20 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432332	WELL	PR	05/17/2014	GW	045-21962	Savage RWF 21-25	PR
432333	WELL	PR	05/19/2014	GW	045-21963	Savage RWF 521-25	PR
432334	WELL	PR	03/01/2014	GW	045-21964	Savage RWF 422-25	PR
432335	WELL	PR	03/01/2014	GW	045-21965	Savage RWF 522-25	PR
432337	WELL	PR	04/12/2014	GW	045-21966	Savage RWF 322-25	PR
432338	WELL	PR	04/12/2014	GW	045-21967	Savage RWF 11-25	PR
432339	WELL	PR	05/19/2014	GW	045-21968	Savage RWF 421-25	PR
432340	WELL	PR	04/12/2014	GW	045-21969	Savage RWF 511-25	PR
432341	WELL	PR	05/18/2014	GW	045-21970	Savage RWF 321-25	PR
432342	WELL	PR	12/12/2013	GW	045-21971	Savage RWF 512-25	PR
432343	WELL	PR	04/08/2014	GW	045-21972	Savage RWF 411-25	PR
432344	WELL	PR	03/01/2014	GW	045-21973	Savage RWF 22-25	PR
432345	WELL	PR	03/11/2014	GW	045-21974	Savage RWF 12-25	PR
432346	WELL	PR	02/12/2014	GW	045-21975	Savage RWF 312-25	PR
432347	WELL	PR	03/01/2014	GW	045-21976	Savage RWF 412-25	PR
432348	WELL	PR	04/08/2014	OW	045-21977	Savage RWF 311-25	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical units at wellhead		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		39.496796,-107.840955
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	432332	Type:	WELL	API Number:	045-21962	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432333	Type:	WELL	API Number:	045-21963	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432334	Type:	WELL	API Number:	045-21964	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432335	Type:	WELL	API Number:	045-21965	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432337	Type:	WELL	API Number:	045-21966	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432338	Type:	WELL	API Number:	045-21967	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432339	Type:	WELL	API Number:	045-21968	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432340	Type:	WELL	API Number:	045-21969	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	432341	Type:	WELL	API Number:	045-21970	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432342	Type:	WELL	API Number:	045-21971	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432343	Type:	WELL	API Number:	045-21972	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432344	Type:	WELL	API Number:	045-21973	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432345	Type:	WELL	API Number:	045-21974	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432346	Type:	WELL	API Number:	045-21975	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432347	Type:	WELL	API Number:	045-21976	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	432348	Type:	WELL	API Number:	045-21977	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			

Comment: Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT