

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2017

Submitted Date:

01/09/2017

Document Number:

680000763**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 324805 QUINT, CRAIG 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 558 CASTLE PINES PKWY UTB4#402City: CASTLE ROCK State: CO Zip: 80104**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|----------------|---------|
| Neher, Gray | 303-771-7777 | bogray@msn.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 212776 | WELL | PR | 12/01/2014 | GW | 061-06136 | T-WEAR 1 | PR |

General Comment:

Location

| | | | |
|--------------------|-------------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through pasture and farm ground | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|-----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by well | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Stickers and Stencils | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|---------------------------|--------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | Dehy with reboiler | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 5 | | |

| | | | | | |
|-----------------------------------|--------------------------------------------------------------------------------------|--|--|-------|--|
| Comment: | 2-chemical tanks w/BMP, Lube oil tank w/BMP, Supply shed, cement slab w/misc supplys | | | | |
| Corrective Action: | | | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | 38.489580,-102.416980 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Berms will need attention soon | | | |
| Corrective Action: | | | | |
| | | | | |
| Corrective Action: | | | | |
| | | | | |
| Corrective Action: | | | | |
| | | | | |

Venting:

| | | | |
|--------------------|----|--|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | | |
| Corrective Action: | | | |
| | | | |
| Corrective Action: | | | |
| | | | |

Flaring:

| | | | |
|--------------------|--|--|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | | |
| Corrective Action: | | | |
| | | | |
| Corrective Action: | | | |
| | | | |

Location Construction

Location ID: 212776 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No issues observed

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

| Inspected Facilities | | | |
|----------------------|-------------------------------------------------------------|-----------------------|------------|
| Facility ID: 212776 | Type: WELL | API Number: 061-06136 | Status: PR |
| Insp. Status: PR | | | |
| Producing Well | | | |
| Comment: | Well not flowing at time of inspection, compressor is down. | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|----------------------------------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401180580 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4047033 |