

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2017

Submitted Date:

01/11/2017

Document Number:

666802875**FIELD INSPECTION FORM**

Loc ID 335050	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> <u>34</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301596	WELL	PR	08/01/2014	GW	045-18200	Hoeppli RWF 443-36	PR
301597	WELL	PR	09/11/2013	GW	045-18201	Hoeppli RWF 344-36	PR
301598	WELL	PR	10/10/2013	GW	045-18202	Hoeppli RWF 334-36	PR
301599	WELL	PR	07/15/2013	GW	045-18203	Hoeppli RWF 632-36	PR
428809	WELL	PR	04/15/2013	GW	045-21472	Hoeppli RWF 513-36	PR
428810	WELL	PR	04/15/2013	GW	045-21473	Hoeppli RWF 324-36	PR
428811	WELL	PR	12/16/2014	GW	045-21474	Hoeppli RWF 413-36	PR
428812	WELL	PR	02/28/2013	GW	045-21475	Hoeppli RWF 314-36	PR
428813	WELL	PR	04/15/2013	GW	045-21476	Hoeppli RWF 24-36	PR
428814	WELL	PR	03/15/2013	GW	045-21477	Hoeppli RWF 424-36	PR
428815	WELL	PR	04/30/2013	GW	045-21478	Hoeppli RWF 323-36	PR
428816	WELL	PR	04/18/2013	GW	045-21479	Hoeppli RWF 322-36	PR
428817	WELL	PR	04/15/2013	GW	045-21480	Hoeppli RWF 13-36	PR
428818	WELL	PR	04/18/2013	GW	045-21481	Hoeppli RWF 423-36	PR
428819	WELL	PR	03/15/2013	GW	045-21482	Hoeppli RWF 14-36	PR
428820	WELL	PR	03/15/2013	GW	045-21483	Hoeppli RMV 145-36	PR
428821	WELL	PR	04/15/2013	GW	045-21484	Hoeppli RWF 523-36	PR
428822	WELL	PR	04/30/2013	GW	045-21485	Hoeppli RWF 23-36	PR
428823	WELL	PR	03/15/2013	GW	045-21486	Hoeppli RWF 414-36	PR
429404	WELL	PR	08/01/2014	GW	045-21547	Hoeppli RWF 333-36	PR
429405	WELL	PR	10/10/2013	GW	045-21548	Hoeppli RWF 44-36	PR
429406	WELL	PR	10/10/2013	GW	045-21549	Hoeppli RWF 34-36	PR
429407	WELL	PR	08/01/2014	GW	045-21550	Hoeppli RWF 532-36	PR
429408	WELL	PR	09/11/2013	GW	045-21551	Hoeppli RWF 433-36	PR

429409	WELL	PR	10/10/2013	GW	045-21552	Hoepli RWF 33-36	PR
429410	WELL	PR	09/11/2013	GW	045-21553	Hoepli RWF 544-36	PR
429411	WELL	PR	07/15/2013	GW	045-21554	Hoepli RWF 43-36	PR
429412	WELL	PR	10/10/2013	GW	045-21555	Hoepli RWF 444-36	PR
429413	WELL	PR	10/10/2013	GW	045-21556	Hoepli RWF 434-36	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-2290-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type	Area	Volume	corrective date
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 8		
Comment:	Chemical unita at wellhead		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		39.481961,-107.836753
Comment:					
Corrective Action:			Date:		

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities						
Facility ID:	301596	Type:	WELL	API Number: 045-18200	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	301597	Type:	WELL	API Number: 045-18201	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	301598	Type:	WELL	API Number: 045-18202	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	301599	Type:	WELL	API Number: 045-18203	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	428809	Type:	WELL	API Number: 045-21472	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	428810	Type:	WELL	API Number: 045-21473	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	428811	Type:	WELL	API Number: 045-21474	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	428812	Type:	WELL	API Number: 045-21475	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:

Facility ID:	428813	Type:	WELL	API Number:	045-21476	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428814	Type:	WELL	API Number:	045-21477	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428815	Type:	WELL	API Number:	045-21478	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428816	Type:	WELL	API Number:	045-21479	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428817	Type:	WELL	API Number:	045-21480	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428818	Type:	WELL	API Number:	045-21481	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428819	Type:	WELL	API Number:	045-21482	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428820	Type:	WELL	API Number:	045-21483	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	428821	Type:	WELL	API Number:	045-21484	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428822	Type:	WELL	API Number:	045-21485	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	428823	Type:	WELL	API Number:	045-21486	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429404	Type:	WELL	API Number:	045-21547	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429405	Type:	WELL	API Number:	045-21548	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429406	Type:	WELL	API Number:	045-21549	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429407	Type:	WELL	API Number:	045-21550	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429408	Type:	WELL	API Number:	045-21551	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	429409	Type:	WELL	API Number:	045-21552	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429410	Type:	WELL	API Number:	045-21553	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429411	Type:	WELL	API Number:	045-21554	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429412	Type:	WELL	API Number:	045-21555	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	429413	Type:	WELL	API Number:	045-21556	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401182239	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4048862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4048862</a>