

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2017

Submitted Date:

01/11/2017

Document Number:

666802878**FIELD INSPECTION FORM**
 Loc ID 432398 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name  | Phone | Email                              | Comment                           |
|---------------|-------|------------------------------------|-----------------------------------|
| , Inspections |       | COGCCInspectionReports@terraep.com | <a href="#">Field Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 432396      | WELL | PR     | 04/30/2014  | GW         | 045-21978 | Savage RWF 314-25 | PR          |
| 432397      | WELL | PR     | 03/07/2014  | OW         | 045-21979 | Savage RWF 24-25  | PR          |
| 432399      | WELL | PR     | 03/07/2014  | OW         | 045-21980 | Savage RWF 14-25  | PR          |
| 432400      | WELL | PR     | 04/30/2014  | GW         | 045-21981 | Savage RWF 413-25 | PR          |
| 432401      | WELL | PR     | 03/07/2014  | OW         | 045-21982 | Savage RWF 424-25 | PR          |
| 432402      | WELL | PR     | 06/02/2014  | GW         | 045-21983 | Savage RWF 13-25  | PR          |
| 432403      | WELL | PR     | 04/30/2014  | GW         | 045-21984 | Savage RWF 414-25 | PR          |
| 432404      | WELL | PR     | 06/30/2014  | GW         | 045-21985 | Savage RWF 23-25  | PR          |
| 432405      | WELL | PR     | 06/30/2014  | GW         | 045-21986 | Savage RWF 423-25 | PR          |
| 432406      | WELL | PR     | 06/30/2014  | GW         | 045-21987 | Savage RWF 313-25 | PR          |
| 432407      | WELL | PR     | 03/07/2014  | OW         | 045-21988 | Savage RWF 324-25 | PR          |
| 432408      | WELL | PR     | 04/30/2014  | GW         | 045-21989 | Savage RWF 514-25 | PR          |
| 432409      | WELL | PR     | 06/30/2014  | GW         | 045-21990 | Savage RWF 323-25 | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | BATTERY              |       |  |
| Comment:           | AIRS ID 045-2354-002 |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  | Date: _____ |
| Corrective Action: |  |             |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| Type                        | #    | Comment                             | Corrective Action | Date  | corrective date |
|-----------------------------|------|-------------------------------------|-------------------|-------|-----------------|
| Horizontal Heated Separator | # 13 |                                     |                   |       |                 |
|                             |      | Comment:                            |                   |       |                 |
|                             |      | Corrective Action:                  |                   | Date: |                 |
| Gas Meter Run               | # 1  |                                     |                   |       |                 |
|                             |      | Comment:                            |                   |       |                 |
|                             |      | Corrective Action:                  |                   | Date: |                 |
| Vertical Separator          | # 2  |                                     |                   |       |                 |
|                             |      | Comment:                            |                   |       |                 |
|                             |      | Corrective Action:                  |                   | Date: |                 |
| Ancillary equipment         | # 2  |                                     |                   |       |                 |
|                             |      | Comment: Chemical units at wellhead |                   |       |                 |
|                             |      | Corrective Action:                  |                   | Date: |                 |
| Plunger Lift                | # 13 |                                     |                   |       |                 |
|                             |      | Comment:                            |                   |       |                 |
|                             |      | Corrective Action:                  |                   | Date: |                 |
| Emission Control Device     | # 1  |                                     |                   |       |                 |
|                             |      | Comment:                            |                   |       |                 |
|                             |      | Corrective Action:                  |                   | Date: |                 |

**Tanks and Berms:**

| Contents           | #                   | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---------------------|----------|-----------|---------|--------|
| PRODUCED WATER     | 2                   | 300 BBLS | STEEL AST |         | ,      |
| Comment:           | Centralized battery |          |           |         |        |
| Corrective Action: |                     |          |           | Date:   |        |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |                       |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
|                    |          |                     |                     |             |                       |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |
| CONDENSATE         | 2        | 300 BBLs            | STEEL AST           |             | 39.493747,-107.837694 |
| Comment:           |          |                     |                     |             |                       |
| Corrective Action: |          |                     |                     |             | Date:                 |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

Venting:

|                    |                        |       |  |
|--------------------|------------------------|-------|--|
| Yes/No             | YES                    |       |  |
| Comment:           | Bradenhead valves open |       |  |
| Corrective Action: |                        | Date: |  |

Flaring:

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |              |       |      |             |           |         |    |               |    |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 432396       | Type: | WELL | API Number: | 045-21978 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432397       | Type: | WELL | API Number: | 045-21979 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432399       | Type: | WELL | API Number: | 045-21980 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432400       | Type: | WELL | API Number: | 045-21981 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432401       | Type: | WELL | API Number: | 045-21982 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432402       | Type: | WELL | API Number: | 045-21983 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432403       | Type: | WELL | API Number: | 045-21984 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 432404       | Type: | WELL | API Number: | 045-21985 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432405 | Type: | WELL | API Number: | 045-21986 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432406 | Type: | WELL | API Number: | 045-21987 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432407 | Type: | WELL | API Number: | 045-21988 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432408 | Type: | WELL | API Number: | 045-21989 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432409 | Type: | WELL | API Number: | 045-21990 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

| Environmental                      |  |
|------------------------------------|--|
| <b>Spill/Remediation:</b>          |  |
| Comment:                           |  |
| Corrective Action:                 | Date:  |
| Emission Control Burner (ECB): YES |  |
| Comment:                           |  |
| Pilot: ON                          | Wildlife Protection Devices (fired vessels): YES |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401182242    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4048865">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4048865</a> |