

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2017

Submitted Date:

01/18/2017

Document Number:

672500313**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 441696 Gomez, Jason 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 20203 HIGHWAY 60City: PLATTEVILLE State: CO Zip: 80651**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Paddington, Dave		dpennington@syrinfo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441687	WELL	DG	09/15/2016	LO	123-41459	Evans 3N-14B-XR	WO
441688	WELL	DG	09/16/2016	LO	123-41460	Evans 4N-14A-XR	WO
441689	WELL	DG	08/11/2016	LO	123-41461	Evans 25N-14B-L	WO
441690	WELL	DG	08/11/2016	LO	123-41462	Evans 9N-14C-L	WO
441691	WELL	DG	08/11/2016	LO	123-41463	Evans 10N-14C-L	WO
441693	WELL	DG	08/11/2016	LO	123-41465	Evans 24N-14B-L	WO
441694	WELL	DG	09/16/2016	LO	123-41466	Evans 29C-14-XR	WO
441697	WELL	DG	09/16/2016	LO	123-41468	Evans 4N-14C-XR	WO
441698	WELL	DG	08/11/2016	LO	123-41469	Evans 9C-14-L	WO
441699	WELL	DG	09/16/2016	LO	123-41470	Evans 29N-14C-XR	WO
441700	WELL	DG	09/16/2016	LO	123-41471	Evans 4N-14B-XR	WO
441701	WELL	DG	09/15/2016	LO	123-41472	Evans 10N-14A-L	WO
441702	WELL	DG	09/15/2016	LO	123-41473	Evans 25C-14-L	WO
441703	WELL	DG	09/16/2016	LO	123-41474	Evans 4C-14-XR	WO
441704	WELL	DG	08/11/2016	LO	123-41475	Evans 24N-14C-L	WO
441705	WELL	DG	09/15/2016	LO	123-41476	Evans 11N-14C-L	WO
441706	WELL	DG	09/15/2016	LO	123-41477	Evans 29N-14A-XR	WO
441707	WELL	DG	08/11/2016	LO	123-41478	Evans 10N-14B-L	WO
441708	WELL	DG	09/16/2016	LO	123-41479	Evans 30N-14B-XR	WO

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 441687	Type: WELL	API Number: 123-41459	Status: DG	Insp. Status: WO
<div> <div>Workover</div> <div> <div>Comment: DRILL OUT</div> <div>Corrective Action:</div> <div>Date:</div> </div> </div>				
Facility ID: 441688	Type: WELL	API Number: 123-41460	Status: DG	Insp. Status: WO
Facility ID: 441689	Type: WELL	API Number: 123-41461	Status: DG	Insp. Status: WO
Facility ID: 441690	Type: WELL	API Number: 123-41462	Status: DG	Insp. Status: WO
Facility ID: 441691	Type: WELL	API Number: 123-41463	Status: DG	Insp. Status: WO
Facility ID: 441693	Type: WELL	API Number: 123-41465	Status: DG	Insp. Status: WO
Facility ID: 441694	Type: WELL	API Number: 123-41466	Status: DG	Insp. Status: WO
Facility ID: 441697	Type: WELL	API Number: 123-41468	Status: DG	Insp. Status: WO
Facility ID: 441698	Type: WELL	API Number: 123-41469	Status: DG	Insp. Status: WO
Facility ID: 441699	Type: WELL	API Number: 123-41470	Status: DG	Insp. Status: WO
Facility ID: 441700	Type: WELL	API Number: 123-41471	Status: DG	Insp. Status: WO
Facility ID: 441701	Type: WELL	API Number: 123-41472	Status: DG	Insp. Status: WO
Facility ID: 441702	Type: WELL	API Number: 123-41473	Status: DG	Insp. Status: WO
Facility ID: 441703	Type: WELL	API Number: 123-41474	Status: DG	Insp. Status: WO
Facility ID: 441704	Type: WELL	API Number: 123-41475	Status: DG	Insp. Status: WO
Facility ID: 441705	Type: WELL	API Number: 123-41476	Status: DG	Insp. Status: WO
Facility ID: 441706	Type: WELL	API Number: 123-41477	Status: DG	Insp. Status: WO
Facility ID: 441707	Type: WELL	API Number: 123-41478	Status: DG	Insp. Status: WO

Facility ID: 441708 Type: WELL API Number: 123-41479 Status: DG Insp. Status: WO

Well Stimulation

Stimulation Company: HALLIBURTON

Stimulation Type: HYDRAULIC FRAC

Observation:

Other: _____

Maximum Casing Recorded: 9000 PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) 9000

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Vehicle Tracking	Pass	
Gravel	Pass					
Ditches	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT