

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2017

Submitted Date:

01/12/2017

Document Number:

674703526**FIELD INSPECTION FORM**
 Loc ID 335318 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259208	WELL	PR	11/01/2015	GW	045-07698	UNOCAL GM 323-28	PR
270269	WELL	PR	11/01/2015	OW	045-09515	WILLIAMS GM 423-28	PR
270340	WELL	PR	11/01/2015	OW	045-09530	WILLIAMS GM 523-28	PR
438598	WELL	PR	04/30/2015	OW	045-22499	WPX GM 522-28	PR
438599	WELL	PR	02/10/2015	GW	045-22500	WPX GM 333-28	PR
438600	WELL	PR	05/04/2015	OW	045-22501	WPX GM 322-28	PR
438601	WELL	PR	02/14/2015	GW	045-22502	WPX GM 533-28	PR
438602	WELL	PR	05/31/2015	OW	045-22503	WPX GM 342-28	PR
438603	WELL	PR	02/14/2015	OW	045-22504	WPX GM 542-28	PR
438604	WELL	PR	05/31/2015	OW	045-22505	WPX GM 432-28	PR
438605	WELL	PR	04/30/2015	OW	045-22506	WPX GM 422-28	PR
438606	WELL	PR	05/08/2015	OW	045-22507	WPX GM 42-28	PR
438607	WELL	PR	02/15/2015	OW	045-22508	WPX GM 433-28	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:	Chemical container at wells			Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 14				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	259208	Type:	WELL	API Number:	045-07698	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	270269	Type:	WELL	API Number:	045-09515	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	270340	Type:	WELL	API Number:	045-09530	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438598	Type:	WELL	API Number:	045-22499	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438599	Type:	WELL	API Number:	045-22500	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438600	Type:	WELL	API Number:	045-22501	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438601	Type:	WELL	API Number:	045-22502	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438602	Type:	WELL	API Number:	045-22503	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID:	438603	Type:	WELL	API Number:	045-22504	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	438604	Type:	WELL	API Number:	045-22505	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	438605	Type:	WELL	API Number:	045-22506	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	438606	Type:	WELL	API Number:	045-22507	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	438607	Type:	WELL	API Number:	045-22508	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
Ditches	Pass					
Seeding	In Process					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401183935	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4050647