

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2017

Submitted Date:

01/19/2017

Document Number:

672500330**FIELD INSPECTION FORM**
 Loc ID 331049 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258104	WELL	PR	09/01/2015	GW	123-20072	MILLAGE 11-10	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		40.420720,-104.543650	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.420720,-104.543650	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258104	Type:	WELL	API Number:	123-20072	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Comment:		PLUMBED TO SURFACE							
Corrective Action:								Date:	

Environmental**Spills/Releases:**

Type of Spill:	_____	Estimated Spill Volume:	_____
Comment:	_____		
Corrective Action:	_____		Date: _____
Reportable:	_____	GPS: Lat _____	Long _____
Proximity to Surface Water:	_____	Depth to Ground Water:	_____

Water Well Complaint:

		Lat	Long
DWR Receipt Num:	_____	Owner Name:	_____
		GPS :	_____

Field Parameters:

Sample Location:	_____	Comment:	_____
------------------	-------	----------	-------

Spill/Remediation:

Comment:	_____		
Corrective Action:	_____	Date:	_____

Emission Control Burner (ECB): YES _____

Comment: _____

Pilot: ON _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT