

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
01/23/2017  
Submitted Date:  
01/23/2017  
Document Number:  
679700342

**FIELD INSPECTION FORM**

Loc ID 322911 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244459	WELL	PR	09/20/2003	GW	123-12254	ROTHE 1-24	EI

**General Comment:**

COGCC Environmental Inspection: Location is P&A, Tank Battery has been decommissioned. See Environmental - Remediation section of this Inspection for requirement to submit produced water vessel assessment results.

**Inspected Facilities**

Facility ID: 244459 Type: WELL API Number: 123-12254 Status: PR Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: Former tank battery area has been graded and straw mulch applied. Operator is directed to submit the results of the assessment of the produced water vessel removal for this location.

Corrective Action: Submit results of the produced water vault removal within 60 days. Reference Tank Battery Facility ID 449006

Date: 03/24/2017

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_