

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2017

Submitted Date:

01/19/2017

Document Number:

674703556**FIELD INSPECTION FORM**

| | | | |
|---|------------------------------------|---|---|
| Loc ID 335901 | Inspector Name: LONGWORTH, MIKE | On-Site Inspection <input type="checkbox"/> | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| 2A Doc Num: _____ | | | Findings: 30 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested |
| Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u> | | | |
| | | | |
| | | | |
| | | | |

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------------|--------------|------------------------------|---|
| Inspections, General | 970-285-2665 | cogcc.inspections@encana.com | EnCana Inspection email |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 297475 | WELL | PR | 10/05/2009 | GW | 045-16853 | N. PARACHUTE EF15B D19B 595 | PR |
| 297825 | WELL | PR | 10/13/2009 | GW | 045-16969 | N. PARACHUTE EF06C D19B 595 | PR |
| 297826 | WELL | PR | 11/01/2009 | GW | 045-16970 | N. PARACHUTE EF10D D19B 595 | PR |
| 297827 | WELL | PR | 10/04/2009 | GW | 045-16971 | N. PARACHUTE EF14C D19B 595 | PR |
| 297828 | WELL | PR | 11/01/2009 | GW | 045-16972 | N. PARACHUTE EF07D D19B 595 | PR |
| 297829 | WELL | PR | 11/01/2009 | GW | 045-16973 | N. PARACHUTE EF06D D19B 595 | PR |
| 297830 | WELL | PR | 11/01/2009 | GW | 045-16974 | N. PARACHUTE EF10C D19B 595 | PR |
| 297831 | WELL | PR | 11/01/2009 | GW | 045-16975 | N. PARACHUTE EF10B D19B 595 | PR |
| 297833 | WELL | PR | 11/01/2009 | GW | 045-16976 | N. PARACHUTE EF10A D19B 595 | PR |
| 297834 | WELL | PR | 10/04/2009 | GW | 045-16977 | N. PARACHUTE EF14A D19B 595 | PR |
| 297836 | WELL | PR | 10/04/2009 | GW | 045-16978 | N. PARACHUTE EF15A D19B 595 | PR |
| 297837 | WELL | PR | 12/01/2009 | GW | 045-16979 | N. PARACHUTE EF08C D19B 595 | PR |
| 297838 | WELL | PR | 12/01/2009 | GW | 045-16980 | N. PARACHUTE EF08B D19B 595 | PR |
| 297839 | WELL | PR | 12/01/2009 | GW | 045-16981 | N. PARACHUTE EF03D D19B 595 | PR |
| 297840 | WELL | PR | 12/01/2009 | GW | 045-16982 | N. PARACHUTE EF02D D19B 595 | PR |
| 297841 | WELL | PR | 06/06/2008 | GW | 045-16983 | N. PARACHUTE EF04B D19B 595 | PR |

| | | | | | | | |
|--------|------|----|------------|----|-----------|--------------------------------|----|
| 297842 | WELL | PR | 11/01/2009 | GW | 045-16984 | N. PARACHUTE EF06A D19B 595 | PR |
| 298923 | WELL | PR | 10/25/2009 | GW | 045-17475 | N. PARACHUTE EF11B D19B 595 | PR |
| 298924 | WELL | PR | 10/04/2009 | GW | 045-17476 | N. PARACHUTE EF11C D19B 595 | PR |
| 298925 | WELL | PR | 09/29/2009 | GW | 045-17477 | N. PARACHUTE EF14B D19B 595 | PR |
| 298926 | WELL | PR | 12/01/2009 | GW | 045-17478 | N. PARACHUTE EF07B D19B 595 | PR |
| 298927 | WELL | PR | 10/03/2009 | GW | 045-17479 | N. PARACHUTE EF11D D19B 595 | PR |
| 298928 | WELL | PR | 12/01/2009 | GW | 045-17480 | N. PARACHUTE EP07C D19B 595 | PR |
| 298936 | WELL | PR | 10/04/2009 | GW | 045-17481 | N. PARACHUTE EF11A D19B 595 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|---------------------------|-------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 4 | | |
| Comment: | Sells | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 20 | | |
| Comment: | Sells | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 20 | | |
| Comment: | gas lift | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Chemical containers at meters | | |

| | | | |
|---------------------|------|-------|--|
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 20 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|-----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 80 bbls | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297475 | Type: | WELL | API Number: | 045-16853 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297825 | Type: | WELL | API Number: | 045-16969 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297826 | Type: | WELL | API Number: | 045-16970 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297827 | Type: | WELL | API Number: | 045-16971 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297828 | Type: | WELL | API Number: | 045-16972 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297829 | Type: | WELL | API Number: | 045-16973 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297830 | Type: | WELL | API Number: | 045-16974 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297831 | Type: | WELL | API Number: | 045-16975 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297833 | Type: WELL | API Number: 045-16976 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297834 | Type: WELL | API Number: 045-16977 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297836 | Type: WELL | API Number: 045-16978 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297837 | Type: WELL | API Number: 045-16979 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297838 | Type: WELL | API Number: 045-16980 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297839 | Type: WELL | API Number: 045-16981 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297840 | Type: WELL | API Number: 045-16982 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 297841 | Type: WELL | API Number: 045-16983 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297842 | Type: | WELL | API Number: | 045-16984 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298923 | Type: | WELL | API Number: | 045-17475 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298924 | Type: | WELL | API Number: | 045-17476 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298925 | Type: | WELL | API Number: | 045-17477 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298926 | Type: | WELL | API Number: | 045-17478 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298927 | Type: | WELL | API Number: | 045-17479 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298928 | Type: | WELL | API Number: | 045-17480 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298936 | Type: | WELL | API Number: | 045-17481 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Pass | |
| | | Ditches | Pass | | | |
| Berms | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401190108 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056031 |