

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2017

Submitted Date:

01/19/2017

Document Number:

674703557**FIELD INSPECTION FORM**
 Loc ID 335579 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:35 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
29	WELL	PR	01/02/2007	GW	045-11674	N. PARACHUTE EF05D E19 595	PR
282300	WELL	PR	03/31/2008	GW	045-11711	N. PARACHUTE E02C-24 E19 595	PR
282301	WELL	PR	12/29/2005	GW	045-11712	N. PARACHUTE EF05C E19 595	PR
282302	WELL	PR	03/27/2008	GW	045-11713	N. PARACHUTE EF02D-24 E19 59	PR
282303	WELL	PR	02/25/2008	GW	045-11714	N.PARACHUTE EF05B-19 E19 59	PR
282304	WELL	PR	01/12/2007	GW	045-11715	N.PARACHUTE EF09B E19 595	PR
282305	WELL	PR	02/01/2014	GW	045-11716	N.PARACHUTE EF09D E19 595	PR
282306	WELL	PR	01/04/2007	GW	045-11717	N. PARACHUTE EFO5B E19 595	PR
291668	WELL	PR	05/27/2008	GW	045-14492	N. PARACHUTE EF09A-24 E19 59	PR
291669	WELL	PR	07/06/2008	GW	045-14491	N. PARACHUTE EF10A-24E19 595	PR
291670	WELL	PR	06/07/2008	GW	045-14490	N. PARACHUTE EF10B-24E19 595	PR
291671	WELL	PR	07/31/2007	GW	045-14489	N. PARACHUTE EF10C-24E19 595	PR
291672	WELL	PR	07/31/2007	GW	045-14488	N.PARACHUTE EF08C-24 E19 59	PR
291674	WELL	PR	07/31/2007	GW	045-14478	N. PARACHUTE EF10D-24E19 595	PR
291675	WELL	PR	11/16/2008	GW	045-14479	N.PARACHUTE EF02B-24 E19 59	PR
291676	WELL	PR	11/06/2008	GW	045-14480	N.PARACHUTE EF08B-24 E19 59	PR

291677	WELL	PR	06/21/2008	GW	045-14481	N.PARACHUTE EF08D-24 E19 59	PR
291681	WELL	PR	02/01/2011	GW	045-14486	N.PARACHUTE EF07B-24 E19 59	PR
291682	WELL	PR	11/13/2008	GW	045-14487	N.PARACHUTE EF07A-24 E19 59	PR
291683	WELL	PR	11/09/2008	GW	045-14485	N. PARACHUTE EF01D-24 E19 59	PR
291684	WELL	PR	11/17/2008	GW	045-14484	N. PARACHUTE EF01B-24 E19 59	PR
291685	WELL	PR	07/03/2008	GW	045-14483	N. PARACHUTE EF07D- 24E19 595	PR
291686	WELL	PR	11/07/2008	GW	045-14482	N. PARACHUTE EF07C-24 E19 59	PR
292401	WELL	PR	11/01/2008	GW	045-14719	N. PARACHUTE EF08A-24 E19 59	PR
292449	WELL	PR	11/07/2008	GW	045-14725	N. PARACHUTE EF 16A-24 E19 5	PR
292450	WELL	PR	11/07/2008	GW	045-14724	N. PARACHUTE EF09C-24 E19 59	PR
293205	WELL	PR	11/20/2008	GW	045-14924	N.PARACHUTE EF02A-24 E19 59	PR
293206	WELL	PR	11/20/2008	GW	045-14925	N.PARACHUTE EF01A-24 E19 59	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment: Gas lift			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment: Sells			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical containers at meters		
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:	sells		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID:	29	Type:	WELL	API Number: 045-11674 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	282300	Type:	WELL	API Number: 045-11711 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	282301	Type:	WELL	API Number: 045-11712 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	282302	Type:	WELL	API Number: 045-11713 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	282303	Type:	WELL	API Number: 045-11714 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	282304	Type:	WELL	API Number: 045-11715 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	282305	Type:	WELL	API Number: 045-11716 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	282306	Type:	WELL	API Number: 045-11717 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:

Facility ID:	291668	Type:	WELL	API Number:	045-14492	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291669	Type:	WELL	API Number:	045-14491	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291670	Type:	WELL	API Number:	045-14490	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291671	Type:	WELL	API Number:	045-14489	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291672	Type:	WELL	API Number:	045-14488	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291674	Type:	WELL	API Number:	045-14478	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291675	Type:	WELL	API Number:	045-14479	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291676	Type:	WELL	API Number:	045-14480	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	291677	Type:	WELL	API Number:	045-14481	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291681	Type:	WELL	API Number:	045-14486	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291682	Type:	WELL	API Number:	045-14487	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291683	Type:	WELL	API Number:	045-14485	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291684	Type:	WELL	API Number:	045-14484	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291685	Type:	WELL	API Number:	045-14483	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291686	Type:	WELL	API Number:	045-14482	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292401	Type:	WELL	API Number:	045-14719	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	292449	Type:	WELL	API Number:	045-14725	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	292450	Type:	WELL	API Number:	045-14724	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293205	Type:	WELL	API Number:	045-14924	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293206	Type:	WELL	API Number:	045-14925	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
		Culverts	Pass			
Berms	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401190109	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4056032