

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2017

Submitted Date:

01/27/2017

Document Number:

666802919**FIELD INSPECTION FORM**
 Loc ID 335312 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270263	WELL	PR	06/25/2004	GW	045-09502	LAZIER 26-2(H26NW)	PR
270271	WELL	PR	06/25/2004	GW	045-09514	BENZEL 26-7B (H26NW)	PR
270290	WELL	PR	06/06/2004	GW	045-09520	BENZEL 26-7B1 (H26NW)	PR
270292	WELL	PR	06/21/2004	GW	045-09521	BENZEL 26-7A (H26NW)	PR

General Comment:[Facilities on location ID 335314](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

0

Comment:

Corrective Action:

Date:

Type: Emission Control Device

0

Comment:

Corrective Action:

Date:

Type: Plunger Lift

4

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

0

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 270263 Type: WELL API Number: 045-09502 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 270271 Type: WELL API Number: 045-09514 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 270290 Type: WELL API Number: 045-09520 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 270292 Type: WELL API Number: 045-09521 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
		Ditches	Pass			
Berms	Pass					

Comment:

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT