

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/23/2017

Submitted Date:

01/23/2017

Document Number:

679700342**FIELD INSPECTION FORM**
 Loc ID 322911 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244459	WELL	PR	09/20/2003	GW	123-12254	ROTHE 1-24	EI

General Comment:

COGCC Environmental Inspection: Location is P&A, Tank Battery has been decommissioned. See Environmental - Remediation section of this Inspection for requirement to submit produced water vessel assessment results.

Environmental**Spill/Remediation:**

Comment: [Former tank battery area has been graded and straw much applied. Operator is directed to submit the results of the assessment of the produced water vessel removal for this location.](#)

Corrective Action: [Submit results of the produced water vault removal within 60 days. Reference Tank Battery Facility ID 449006](#)

Date: 03/24/2017

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401191637	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4057599