

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/27/2017

Submitted Date:

01/30/2017

Document Number:

666802915**FIELD INSPECTION FORM**

Loc ID 335185 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210958	WELL	PR	08/18/1995	GW	045-06716	JOLLEY 20-6 1	PR
289479	WELL	PR	08/04/2009	GW	045-13772	GGU JOLLEY 44C-20-691	PR
289480	WELL	PR	06/29/2007	GW	045-13771	GGU JOLLEY 44A-20-691	PR
289777	WELL	PR	07/16/2009	GW	045-13881	GGU JOLLEY 43B-20-691	PR
289778	WELL	PR	07/07/2007	GW	045-13880	GGU JOLLEY 43D-20-691	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 5

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 5

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		39.509887,-107.570696

Comment:

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	210958	Type:	WELL	API Number:	045-06716	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289479	Type:	WELL	API Number:	045-13772	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289480	Type:	WELL	API Number:	045-13771	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289777	Type:	WELL	API Number:	045-13881	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289778	Type:	WELL	API Number:	045-13880	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	301699	1433938	
	301699	1433938	