



**Inspected Facilities**

Facility ID: 412904 Type: WELL API Number: 057-06499 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Inspector on location to witness bradenhead test. Form 42 document number 401188588.	waldrone	01/26/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401195189	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4060992">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4060992</a>