

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2017

Submitted Date:

02/02/2017

Document Number:

666802930**FIELD INSPECTION FORM**

Loc ID 335541 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289392	WELL	PR	06/18/2011	GW	045-13754	O'Toole A1	PR
289393	WELL	PR	06/18/2011	GW	045-13753	O'Toole A2	PR
289394	WELL	PR	07/14/2007	GW	045-13752	O'TOOLE A3	PR
289395	WELL	PR	02/21/2007	GW	045-13751	O'TOOLE A4	PR
301931	WELL	PR	08/01/2012	GW	045-18327	O'Toole A6	PR
301932	WELL	PR	02/17/2012	GW	045-18328	O'Toole A7	PR
301933	WELL	PR	08/01/2012	GW	045-18329	O'Toole A5	PR
301934	WELL	PR	06/17/2011	GW	045-18330	O'Toole A8	PR
421530	WELL	PR	06/19/2011	GW	045-20400	O'Toole A9	PR

**General Comment:**[Action items noted on previos inspection have been satisfied](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 9

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 9

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,

Comment: Centralized battery

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.522618,-107.664375	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID:	289392	Type:	WELL	API Number: 045-13754 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	289393	Type:	WELL	API Number: 045-13753 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	289394	Type:	WELL	API Number: 045-13752 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	289395	Type:	WELL	API Number: 045-13751 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	301931	Type:	WELL	API Number: 045-18327 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	301932	Type:	WELL	API Number: 045-18328 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	301933	Type:	WELL	API Number: 045-18329 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	301934	Type:	WELL	API Number: 045-18330 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		



Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Mulching	Pass					
Culverts	Pass					
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			
		Waddles	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT