

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2017

Submitted Date:

01/27/2017

Document Number:

666802907**FIELD INSPECTION FORM**
 Loc ID 335314 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email                        | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General |       | cogcc.inspections@encana.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 270262      | WELL | PR     | 06/21/2004  | GW         | 045-09504 | BENZEL 26-8C (H26NW) | PR          |
| 270264      | WELL | PR     | 06/01/2004  | GW         | 045-09505 | BENZEL 26-8B (H26NW) | PR          |
| 270267      | WELL | PR     | 06/19/2004  | GW         | 045-09508 | BENZEL 26-8A (H26NW) | PR          |
| 270276      | WELL | PR     | 06/18/2004  | GW         | 045-09509 | BENZEL 26-9B (H26NW) | PR          |
| 271411      | WELL | PR     | 07/19/2004  | GW         | 045-09877 | LAZIER 26-1A(H26NW)  | PR          |

**General Comment:**[Shared facilities with location ID 335312](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

|                                 |     |       |  |
|---------------------------------|-----|-------|--|
| Type: Gas Meter Run             | # 1 |       |  |
| Comment:                        |     |       |  |
| Corrective Action:              |     | Date: |  |
| Type: Plunger Lift              | # 5 |       |  |
| Comment:                        |     |       |  |
| Corrective Action:              |     | Date: |  |
| Type: Vertical Heated Separator | # 9 |       |  |
| Comment:                        |     |       |  |
| Corrective Action:              |     | Date: |  |
| Type: Emission Control Device   | # 1 |       |  |
| Comment:                        |     |       |  |
| Corrective Action:              |     | Date: |  |

**Tanks and Berms:**

| Contents           | #                   | Capacity | Type      | Tank ID | SE GPS |  |
|--------------------|---------------------|----------|-----------|---------|--------|--|
| METHANOL           | 1                   | 1000 GAL | STEEL AST |         | ,      |  |
| Comment:           | Centralized battery |          |           |         |        |  |
| Corrective Action: |                     |          |           |         | Date:  |  |

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     | Date:               |             |

|                    |          |                     |                     |             |                       |       |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|-------|
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| CONDENSATE         | 3        | 500 BBLs            | STEEL AST           |             | 39.498465,-107.737470 |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Paint</b>       |          |                     |                     |             |                       |       |
| Condition          | Adequate |                     |                     |             |                       |       |
| Other (Content)    |          |                     |                     |             |                       |       |
| Other (Capacity)   |          |                     |                     |             |                       |       |
| Other (Type)       |          |                     |                     |             |                       |       |
| <b>Berms</b>       |          |                     |                     |             |                       |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Venting:</b>    |          |                     |                     |             |                       |       |
| Yes/No             | NO       |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <b>Flaring:</b>    |          |                     |                     |             |                       |       |
| Type               |          |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |

| Inspected Facilities  |              |       |      |             |           |         |    |               |    |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 270262       | Type: | WELL | API Number: | 045-09504 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 270264       | Type: | WELL | API Number: | 045-09505 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 270267       | Type: | WELL | API Number: | 045-09508 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 270276       | Type: | WELL | API Number: | 045-09509 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 271411       | Type: | WELL | API Number: | 045-09877 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |

| Environmental                      |  |
|------------------------------------|--|
| <b>Spill/Remediation:</b>          |  |
| Comment:                           |  |
| Corrective Action:                 | Date:  |
| Emission Control Burner (ECB): YES |  |
| Comment:                           |  |
| Pilot: ON                          | Wildlife Protection Devices (fired vessels): YES |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            |                         |                       |               |                          |         |
|                  |                 | Culverts                | Pass                  |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401196004    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4061839">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4061839</a> |