



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Survey Line surrounding lease.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 251023 Type: WELL API Number: 123-18826 Status: TA Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 6890-5698

Cement Volume (sx): 40 sacks

Good Return During Job: YES

Cement Type: Type G

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Routine PA. Company representative on location: Jay Chandler.	carlilec	02/03/2017