



photo 1: Facing southeast along the former access road.



photo 2: Facing southeast toward the location.



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.



photo 7: Vegetation has not established at the location and the soils are compacted.



photo 8: Facing east toward the surrounding undisturbed pasture (reference area).