



**photo 1:** Center of the location facing north.



**photo 2:** Center of the location facing west.



**photo 3:** Center of the location facing south.



**photo 4:** Center of the location facing east.



**photo 5:** View of groundcover. There is no vegetation establishment and soils seem to be compacted.



**photo 6:** Facing east toward surrounding undisturbed pasture (reference area).