

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2017

Submitted Date:

02/02/2017

Document Number:

666802926**FIELD INSPECTION FORM**
 Loc ID 311676 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment                         |
|-----------------|--------------|----------------------------|---------------------------------|
| Knudson, Dwayne | 970-456-3335 | dknudson@ursaresources.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 284376      | WELL | PR     | 03/11/2007  | GW         | 045-12159 | DEVER A3      | PR          |
| 284377      | WELL | PR     | 08/23/2011  | GW         | 045-12158 | DEVER A2      | PR          |
| 284378      | WELL | PR     | 11/22/2006  | GW         | 045-12157 | DEVER A1      | PR          |
| 288803      | WELL | PR     | 04/05/2008  | GW         | 045-13571 | DEVER A12     | PR          |
| 289034      | WELL | PR     | 11/20/2007  | GW         | 045-13635 | DEVER A9      | PR          |
| 289035      | WELL | PR     | 11/20/2007  | GW         | 045-13634 | DEVER A8      | PR          |
| 289036      | WELL | PR     | 01/23/2009  | GW         | 045-13633 | DEVER A6      | PR          |
| 289039      | WELL | PR     | 01/22/2007  | GW         | 045-13630 | DEVER A13     | PR          |
| 289040      | WELL | PR     | 01/26/2009  | GW         | 045-13629 | DEVER A10     | PR          |
| 294072      | WELL | PR     | 12/24/2007  | GW         | 045-15232 | DEVER A16     | PR          |

**General Comment:**[Action required items noted on previous inspection for weeds and Anchor have been satisfied](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 12

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 10

Comment: Corrective Action: Date: 

Type: Emission Control Device

# 1

Comment: Corrective Action: Date: **Tanks and Berms:**

| Contents                                | # | Capacity | Type      | Tank ID | SE GPS |                            |
|---|---|----------|-----------|---------|--------|----------------------------|
| PRODUCED WATER                          | 1 | 300 BBLS | STEEL AST |         | ,      |                            |
| Comment: Centralized battery            |   |          |           |         |        |                            |
| Corrective Action: <input type="text"/> |   |          |           |         |        | Date: <input type="text"/> |

**Paint**

Condition Adequate

Other (Content) Other (Capacity) Other (Type) **Berms**

| Type               | Capacity |   | Permeability (Wall) |           | Permeability (Base) |         | Maintenance |                       |       |  |
|--------------------|----------|---|---------------------|-----------|---------------------|---------|-------------|-----------------------|-------|--|
|                    |          |   |                     |           |                     |         |             |                       |       |  |
| Comment:           |          |   |                     |           |                     |         |             |                       |       |  |
| Corrective Action: |          |   |                     |           |                     |         |             |                       | Date: |  |
| Contents           |          | # | Capacity            | Type      |                     | Tank ID |             | SE GPS                |       |  |
| CONDENSATE         |          | 3 | 300 BBLS            | STEEL AST |                     |         |             | 39.521633,-107.708977 |       |  |
| Comment:           |          |   |                     |           |                     |         |             |                       |       |  |

|                    |  |  |  |  |       |  |
|--------------------|--|--|--|--|-------|--|
| Corrective Action: |  |  |  |  | Date: |  |
|--------------------|--|--|--|--|-------|--|

**Paint**

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |              |       |      |             |           |         |    |               |    |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 284376       | Type: | WELL | API Number: | 045-12159 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 284377       | Type: | WELL | API Number: | 045-12158 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 284378       | Type: | WELL | API Number: | 045-12157 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288803       | Type: | WELL | API Number: | 045-13571 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 289034       | Type: | WELL | API Number: | 045-13635 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 289035       | Type: | WELL | API Number: | 045-13634 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 289036       | Type: | WELL | API Number: | 045-13633 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 289039       | Type: | WELL | API Number: | 045-13630 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 289040 | Type: | WELL | API Number: | 045-13629 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 294072 | Type: | WELL | API Number: | 045-15232 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Ditches                 | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Slope Roughening | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401200508    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066072</a> |