

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2017

Submitted Date:

02/03/2017

Document Number:

674004813**FIELD INSPECTION FORM**
 Loc ID 305627 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name  | Phone | Email                         | Comment                         |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections |       | COGCCinspections@Anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 280421      | WELL | PR     | 04/24/2011  | GW         | 123-23266 | WEBBER 17-3   | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| <b>Fencing/:</b>   |                   |       |  |
| Type               | IGNITOR/COMBUSTOR |       |  |
| Comment:           | Pipe              |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | WELLHEAD          |       |  |
| Comment:           | Pipe              |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | SEPARATOR         |       |  |
| Comment:           | Barb Wire         |       |  |
| Corrective Action: |                   | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Plunger Lift                | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |

|                               |     |       |  |
|-------------------------------|-----|-------|--|
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |
| Type: Gas Meter Run           | # 1 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |
| Type: Emission Control Device | # 1 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |                       |       |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |       |
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | 40.258190,-104.758170 |       |
| Comment:           |   |          |           |         |                       |       |
| Corrective Action: |   |          |           |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          | Date:               |                     |             |

**Venting:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Yes/No             | YES |       |  |
| Comment:           |     |       |  |
| Corrective Action: |     |       |  |
|                    |     | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  |       |  |
|                    |  | Date: |  |

| Inspected Facilities |        |                                |      |             |           |         |    |               |    |
|----------------------|--------|--------------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 280421 | Type:                          | WELL | API Number: | 123-23266 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |                                |      |             |           |         |    |               |    |
| Comment:             |        | PR                             |      |             |           |         |    |               |    |
| Corrective Action:   |        |                                |      |             |           |         |    | Date:         |    |
| BradenHead           |        |                                |      |             |           |         |    |               |    |
| Comment:             |        | Bradenhead plumbed to surface. |      |             |           |         |    |               |    |
| Corrective Action:   |        |                                |      |             |           |         |    | Date:         |    |

**Environmental****Spills/Releases:**

|                             |       |                         |             |
|-----------------------------|-------|-------------------------|-------------|
| Type of Spill:              | _____ | Estimated Spill Volume: | _____       |
| Comment:                    | _____ |                         |             |
| Corrective Action:          | _____ |                         | Date: _____ |
| Reportable:                 | _____ | GPS: Lat _____          | Long _____  |
| Proximity to Surface Water: | _____ | Depth to Ground Water:  | _____       |

**Water Well Complaint:**

|                  |       |             |       |
|------------------|-------|-------------|-------|
|                  |       | Lat         | Long  |
| DWR Receipt Num: | _____ | Owner Name: | _____ |
|                  |       | GPS :       | _____ |

**Field Parameters:**

|                  |       |          |       |
|------------------|-------|----------|-------|
| Sample Location: | _____ | Comment: | _____ |
|------------------|-------|----------|-------|

**Spill/Remediation:**

|                    |       |       |       |
|--------------------|-------|-------|-------|
| Comment:           | _____ |       |       |
| Corrective Action: | _____ | Date: | _____ |

Emission Control Burner (ECB): YES \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: ON \_\_\_\_\_ Wildlife Protection Devices (fired vessels): YES \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment                             | User     | Date       |
|-------------------------------------|----------|------------|
| <a href="#">Routine inspection.</a> | carlilec | 02/03/2017 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401202049    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4067897">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4067897</a> |