



**photo 1:** The culvert along the access road near the location has filled in with sediment.



**photo 2:** There is a sign for pit closure.





**photo 3:** There is a dripping water leak at the wellhead.



**photo 4:** There was oil noticed on the engine skid.





**photo 5:** Facing east toward the location.