

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2017

Submitted Date:

02/13/2017

Document Number:

666802938**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 335410 Murray, Richard 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277037	WELL	PR	03/17/2009	GW	045-10587	GMR 27-2D (H27NW)	PR
296133	WELL	PR		GW	045-15913	GMR 22-16D (H27NW)	PR
296134	WELL	PR		GW	045-15914	GMU 27-1C (H27NW)	PR
296135	WELL	PR		GW	045-15915	GMU 26-4B (H27NW)	PR
413168	WELL	PR	07/13/2010	GW	045-18754	GMU 27-8D (H27NW)	PR
413169	WELL	PR	07/13/2010	GW	045-18725	GMU 27-8C2 (H27NW)	PR
413170	WELL	PR	07/10/2010	GW	045-18726	GMU 26-5A2(H27NW)	PR
413171	WELL	PR	07/10/2010	GW	045-18727	GMU 26-4B2 (H27NW)	PR
413172	WELL	PR	07/10/2010	GW	045-18728	GMU 27-1C2 (H27NW)	PR
413173	WELL	PR	07/13/2010	GW	045-18729	GMU 27-8C1 (H27NW)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

1

Comment: Chemical unit at wellhead

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

9

Comment:

Corrective Action:

Date:

Type: Plunger Lift

10

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

METHANOL

1

1000 GAL

STEEL AST

,

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLS	STEEL AST		39.499326,-107.755648	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	277037	Type:	WELL	API Number:	045-10587	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	296133	Type:	WELL	API Number:	045-15913	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	296134	Type:	WELL	API Number:	045-15914	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	296135	Type:	WELL	API Number:	045-15915	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	413168	Type:	WELL	API Number:	045-18754	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	413169	Type:	WELL	API Number:	045-18725	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	413170	Type:	WELL	API Number:	045-18726	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	413171	Type:	WELL	API Number:	045-18727	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID:	413172	Type:	WELL	API Number:	045-18728	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	413173	Type:	WELL	API Number:	045-18729	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
Gravel	Pass					
Berms	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT