



**Inspected Facilities**

Facility ID: 443821 Type: WELL API Number: 123-42389 Status: DG Insp. Status: WK

**Complaint**

Comment: [Complaint #:200441031](#)  
[Field Inspector Assigned: Jeff Rickard](#)  
[Location #: 332882](#)  
[Inspection Document #: 674103934](#)  
[Nature of complaint: Noise](#)  
[If Sound GPS Coordinates of Survey Location: NA](#)  
[Inspection Observations:](#)  
 OGCC inspector was on location on 2/13/17, winds were still too high to run a sound survey being 13 mph out of the north. OGCC inspector will return to location on 2/14/17 to try and run a sound survey if wind conditions allow.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Well Stimulation**

Stimulation Company: Cal Frac Stimulation Type: HYDRAULIC FRAC  
 Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI Tubing: \_\_\_\_\_  
 Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
 Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
 Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: \_\_\_\_\_ Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [Braden head is exposed at surface.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>Complaint #:200441031</p> <p>Field Inspector Assigned: Jeff Rickard</p> <p>Location #: 332882</p> <p>Inspection Document #: 674103934</p> <p>Nature of complaint: Noise</p> <p>If Sound GPS Coordinates of Survey Location: NA</p> <p>Inspection Observations:</p> <p>OGCC inspector was on location on 2/13/17, winds were still too high to run a sound survey being 13 mph out of the north. OGCC inspector will return to location on 2/14/17 to try and run a sound survey if wind conditions allow.</p>	rickardj	02/13/2017