

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2017

Submitted Date:

02/09/2017

Document Number:

675203801**FIELD INSPECTION FORM**
 Loc ID 334359 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|-----------------------------|---|
| Bankert, Wayne | (970) 683-5419 | wbankert@laramie-energy.com | Senior Regulatory & Environmental Coordinator |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 285098 | WELL | PR | 02/01/2011 | GW | 045-12376 | REPO A11-34B | PR |
| 286086 | WELL | PR | 01/12/2010 | GW | 045-12614 | REPO A-10-34D | PR |
| 295579 | WELL | PR | 03/30/2009 | GW | 045-15791 | REPO 34-7D | PR |
| 295580 | WELL | PR | 02/18/2010 | GW | 045-15790 | REPO 34-11C | PR |
| 295582 | WELL | PR | 01/27/2010 | GW | 045-15788 | REPO 34-7B | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------|----------|-----------|---------|----------------------------|
| CONDENSATE | 2 | 200 BBLs | STEEL AST | | , |
| Comment: | <input type="text"/> | | | | |
| Corrective Action: | <input type="text"/> | | | | Date: <input type="text"/> |

Paint

| | | |
|------------------|----------------------|--|
| Condition | Adequate | |
| Other (Content) | <input type="text"/> | |
| Other (Capacity) | <input type="text"/> | |
| Other (Type) | <input type="text"/> | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------|---------------------|---------------------|----------------------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | <input type="text"/> | | | |
| Corrective Action: | <input type="text"/> | | | Date: <input type="text"/> |

Venting:

| | | |
|--------------------|----------------------|----------------------------|
| Yes/No | NO | |
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

Flaring:

| | |
|------|----------------------|
| Type | <input type="text"/> |
|------|----------------------|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>285098</u> | Type: <u>WELL</u> | API Number: <u>045-12376</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>286086</u> | Type: <u>WELL</u> | API Number: <u>045-12614</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>295579</u> | Type: <u>WELL</u> | API Number: <u>045-15791</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>295580</u> | Type: <u>WELL</u> | API Number: <u>045-15790</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>295582</u> | Type: <u>WELL</u> | API Number: <u>045-15788</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |
| Compaction | Pass | Gravel | Pass | | | |
| Berms | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401206250 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4071848 |