

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/17/2017

Document Number:

674703629**FIELD INSPECTION FORM**

Loc ID 334895 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259548	WELL	PR	06/05/2002	GW	045-07742	UNOCAL GM 246-1	PR
275226	WELL	PR	07/27/2005	GW	045-13475	WILLIAMS GM 542-1	PR
275227	WELL	PR	07/27/2005	GW	045-13474	WILLIAMS GM 442-1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 259548 Type: WELL API Number: 045-07742 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 275226 Type: WELL API Number: 045-13475 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 275227 Type: WELL API Number: 045-13474 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Ditches	Pass					
Compaction	Pass					
		Gravel	Pass			
		Compaction	Pass			
		Ditches	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT