

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2017

Submitted Date:

02/12/2017

Document Number:

682600268**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: Kosola, Jason On-Site Inspection ☐  
 2A Doc Num: \_\_\_\_\_
**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Stutz, Bill	(719) 767-8805	wstutz@mulldrlg.com	
CARL, SMALLEY	(719) 767-8805	CSmalley@MULLDRLG.com	MULL ENVIRONMENTAL
Akers, Tracy	(719) 767-8805	takers@mulldrlg.com	Production Laborer

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449146	SPILL OR RELEASE	AC	02/08/2017		-	NORTH WEST ARAPAHOE UNIT 27	EI

**General Comment:**

This is an environmental inspection in response to Spill #449146 on the NWAU #27 well.

Attached photos indicate that the spill was not confined to the well pad as operator described in Form 19 401204571 and in subsequent request for variance for soil sampling. The spill sprayed oil onto adjacent crops to the south and east of the wellhead (see attached map). A small excavation near the wellhead showed the presence of stained soil with a strong hydrocarbon smell. Confirmation samples need to be obtained by operator to delineate extent of spill and ensure remaining soils are compliant with COGCC Table 910-1.



**Environmental****Spill/Remediation:**Comment: [Operator stated on Form 19 401204571 that a truck was dispatched to recover free fluids.](#)Corrective Action: [Per Rule 907.b.2 the operator should submit documentation of E&P waste disposal on Form 19 Subsequent.](#)

Date: 02/28/2017

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401208097	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4073468">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4073468</a>
682600269	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4073465">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4073465</a>
682600270	Spill map	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4073466">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4073466</a>