

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2017

Submitted Date:

02/03/2017

Document Number:

672500378**FIELD INSPECTION FORM**

| Loc ID<br>444427   | Inspector Name:<br>Gomez, Jason | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____               | <b>Status Summary:</b><br><input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>4 Number of Comments<br>0 Number of Corrective Actions<br><input type="checkbox"/> Corrective Action Response Requested |              |                     |             |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
|--|---------------------------------|---|---------------------------------|--|--------------|---------------------|-------------|------------|---------|---------------|-------------------------------|---------------------------------|------|----|------------|----|-----------|---------------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|----------------|----|--------|------|----|------------|----|-----------|----------------|----|--------|------|----|------------|----|-----------|---------------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|---------------------|----|--------|------|----|------------|----|-----------|--------------------|----|
| <b>Operator Information:</b><br>OGCC Operator Number: <u>47120</u><br>Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u><br>Address: <u>P O BOX 173779</u><br>City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>  |                                 |   |                                 |  |              |                     |             |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| <b>Contact Information:</b><br><table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>,</td> <td></td> <td>COGCCinspections@anadarko.com</td> <td><a href="#">All Inspections</a></td> </tr> </table>   |                                 |   |                                 |  | Contact Name | Phone               | Email       | Comment    | ,       |               | COGCCinspections@anadarko.com | <a href="#">All Inspections</a> |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| Contact Name   | Phone                           | Email                                       | Comment                         |  |              |                     |             |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| ,  |                                 | COGCCinspections@anadarko.com               | <a href="#">All Inspections</a> |  |              |                     |             |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| <b>Inspected Facilities:</b><br><table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>444425</td><td>WELL</td><td>DG</td><td>11/15/2016</td><td>LO</td><td>123-42623</td><td>JAGUAR FED 35N-35HZ</td><td>DG</td></tr> <tr><td>444426</td><td>WELL</td><td>DG</td><td>11/17/2016</td><td>LO</td><td>123-42624</td><td>JAGUAR 36C-35HZ</td><td>DG</td></tr> <tr><td>444428</td><td>WELL</td><td>DG</td><td>11/19/2016</td><td>LO</td><td>123-42625</td><td>JAGUAR 3N-14HZ</td><td>DG</td></tr> <tr><td>444429</td><td>WELL</td><td>DG</td><td>11/21/2016</td><td>LO</td><td>123-42626</td><td>JAGUAR 3C-14HZ</td><td>DG</td></tr> <tr><td>444430</td><td>WELL</td><td>DG</td><td>11/20/2016</td><td>LO</td><td>123-42627</td><td>JAGUAR FED 29N-14HZ</td><td>DG</td></tr> <tr><td>444431</td><td>WELL</td><td>DG</td><td>11/18/2016</td><td>LO</td><td>123-42628</td><td>JAGUAR 28C-14HZ</td><td>DG</td></tr> <tr><td>444432</td><td>WELL</td><td>DG</td><td>11/14/2016</td><td>LO</td><td>123-42629</td><td>JAGUAR FED 35C-35HZ</td><td>DG</td></tr> <tr><td>444433</td><td>WELL</td><td>DG</td><td>11/13/2016</td><td>LO</td><td>123-42630</td><td>JAGUAR FED 6S-35HZ</td><td>DG</td></tr> </tbody> </table> |                                 |   |                                 | Facility ID  | Type         | Status              | Status Date | Well Class | API Num | Facility Name | Insp Status                   | 444425                          | WELL | DG | 11/15/2016 | LO | 123-42623 | JAGUAR FED 35N-35HZ | DG | 444426 | WELL | DG | 11/17/2016 | LO | 123-42624 | JAGUAR 36C-35HZ | DG | 444428 | WELL | DG | 11/19/2016 | LO | 123-42625 | JAGUAR 3N-14HZ | DG | 444429 | WELL | DG | 11/21/2016 | LO | 123-42626 | JAGUAR 3C-14HZ | DG | 444430 | WELL | DG | 11/20/2016 | LO | 123-42627 | JAGUAR FED 29N-14HZ | DG | 444431 | WELL | DG | 11/18/2016 | LO | 123-42628 | JAGUAR 28C-14HZ | DG | 444432 | WELL | DG | 11/14/2016 | LO | 123-42629 | JAGUAR FED 35C-35HZ | DG | 444433 | WELL | DG | 11/13/2016 | LO | 123-42630 | JAGUAR FED 6S-35HZ | DG |
| Facility ID  | Type                            | Status                                      | Status Date                     | Well Class   | API Num      | Facility Name       | Insp Status |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444425   | WELL                            | DG  | 11/15/2016                      | LO   | 123-42623    | JAGUAR FED 35N-35HZ | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444426   | WELL                            | DG  | 11/17/2016                      | LO   | 123-42624    | JAGUAR 36C-35HZ     | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444428   | WELL                            | DG  | 11/19/2016                      | LO   | 123-42625    | JAGUAR 3N-14HZ      | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444429   | WELL                            | DG  | 11/21/2016                      | LO   | 123-42626    | JAGUAR 3C-14HZ      | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444430   | WELL                            | DG  | 11/20/2016                      | LO   | 123-42627    | JAGUAR FED 29N-14HZ | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444431   | WELL                            | DG  | 11/18/2016                      | LO   | 123-42628    | JAGUAR 28C-14HZ     | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444432   | WELL                            | DG  | 11/14/2016                      | LO   | 123-42629    | JAGUAR FED 35C-35HZ | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| 444433   | WELL                            | DG  | 11/13/2016                      | LO   | 123-42630    | JAGUAR FED 6S-35HZ  | DG          |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |
| <b>General Comment:</b><br><br><br><br><br><br><br><br><br><br><br>  |                                 |   |                                 |  |              |                     |             |            |         |               |                               |                                 |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                 |    |        |      |    |            |    |           |                     |    |        |      |    |            |    |           |                    |    |

**Inspected Facilities**

Facility ID: 444425 Type: WELL API Number: 123-42623 Status: DG Insp. Status: DG

**Complaint**

Comment: 200441018

Corrective Action:

Date:

**Well Drilling**

**Rig:** Rig Name: EXTREME 24 Pusher/Rig Manager: TRAVIS  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: WASTE MAGANEMENT

Comment: ALL LIGHTS ON RIG AND EQUIPMENT POINTED DOWN AND TOWARD THE CENTER OF LOCATION

Corrective Action:

Date:

Facility ID: 444426 Type: WELL API Number: 123-42624 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment:

Corrective Action:

Date:

Facility ID: 444428 Type: WELL API Number: 123-42625 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

|                    |  |       |
|--------------------|--|-------|
| <u>Comment:</u>    |  |       |
| Corrective Action: |  | Date: |

Facility ID: 444429 Type: WELL API Number: 123-42626 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 444430 Type: WELL API Number: 123-42627 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 444431 Type: WELL API Number: 123-42628 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 444432 Type: WELL API Number: 123-42629 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 444433 Type: WELL API Number: 123-42630 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  | Material Handling And Spill Prevention | Pass                     |         |
| Ditches          | Pass            |                         |                       | Vehicle Tracking                       | Pass                     |         |
| Compaction       | Pass            | Compaction              | Pass                  | Covering Materials                     | Pass                     |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| INSPECTION WAS BASED ON COMPLAINT #200441018. NO VIOLATIONS OF COGCC RULES WERE OBSERVED AT THE TIME OF INSPECTION | gomezj | 02/03/2017 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401210471    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075550">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075550</a> |